0,3

FINAL REPORT FOR REMEDIATION OF LOCATIONS IN GRANITE CITY, MADISON, AND VENICE, ILLINOIS ASSOCIATED WITH NL INDUSTRIES/TARACORP SUPERFUND SITE

PRE-PLACED CONTRACT NO. DACA45-96-D-0014 DELIVERY ORDER NO. 0005

Submitted by:

OHM Remediation Services Corp. *Midwest Region*

Prepared by:

Tom Warren Project Manager

October 16, 1998 Project 19531

This information is the exclusive property of the party to whom it is addressed. OHM Remediation Services Corp. assumes no responsibility or liability for the reliance hereon or use hereof by anyone other than the party to whom it is addressed. ©1998 OHM Remediation Services Corp.



TABLE OF CONTENTS

- 1.0 INTRODUCTION
 - 1.1 SITE HISTORY
 - 1.2 DOCUMENT ORGANIZATION
- 2.0 SCOPE OF WORK
 - 2.1 PREPARATION OF SITE-SPECIFIC PLANS
 - 2.2 SITE ADMINISTRATION/LOGISTICAL SUPPORT
 - 2.3 MOBILIZATION/DEMOBILIZATION
 - 2.4 SITE PREPARATION AND TEARDOWN
 - 2.5 OPERATIONAL SCOPE OF WORK PERFORMED
 - 2.6 SAMPLING AND ANALYSIS
 - 2.7 TRANSPORTATION AND DISPOSAL
- 3.0 TECHNICAL APPROACH
 - 3.1 PRE-CONSTRUCTION ACTIVITIES
 - 3.2 SAMPLING AND ANALYSIS
 - 3.3 CHEMICAL DATA ACQUISITION PLAN AMENDMENTS/ADJUSTMENTS
 - 3.4 TRANSPORTATION AND DISPOSAL
- 4.0 HEALTH AND SAFETY SUMMARY
 - 4.1 PROJECT SUMMARY AND CONCLUSIONS
 - 4.2 SITE SAFETY AND HEALTH PLAN EVALUATION
 - 4.3 SITE SAFETY
 - 4.4 EXPOSURE MONITORING
- 5.0 QUANTITY SUMMARY TABLE
- 6.0 VERIFICATION ANALYTICAL SUMMARY TABLE
 - 6.1 STACK EMISSION SITES
- 7.0 PHOTO REPRESENTATION

APPENDIX A - FLOW CHARTS
APPENDIX B - REMEDIAL LOCATION WORK DESCRIPTIONS
APPENDIX C - EASEMENT INFORMATION

1.0 INTRODUCTION

The United States Army Corps of Engineers (USACE) tasked OHM Remediation Services Corp. (OHM), a wholly owned subsidiary of OHM Corporation, under the Pre-Placed Contract No. DACA45-96-D-0014, Delivery Order (DO) No. 005, to perform remediation of Stack Emission sites at various locations associated with the NL Industries/Taracorp Superfund Site (NL Site) in Granite City, Madison, and Venice, Illinois.

1.1 SITE HISTORY

The NL Site includes the NL Industries/Taracorp Plant, a former secondary lead smelting operation located at 16th and Cleveland Boulevard in Granite City, Illinois. Prior to 1903, the plant included various smelting related equipment and processes. From 1903 to 1983, secondary lead smelting occurred on site. These activities were discontinued during 1983 and the equipment was dismantled.

In July 1981, St. Louis Lead Recyclers, Inc. (SLLR) began using equipment on adjacent property owned by Trust 454 to separate components of the Taracorp waste pile. The objective was to recycle lead bearing materials to the furnaces at Taracorp and send hard rubber off site for recycling. SLLR continued operations until March 1983 when it shut down its equipment. Residuals from the operation remain on Trust 454 property as does some equipment.

A State Implementation Plan for Granite City, Illinois was published in September 1983 by the Illinois Environmental Protection Agency (IEPA). The IEPA's report indicated the lead non-attainment problem for air emissions in Granite City, Illinois, were in large part due to emissions associated with the operation of the secondary lead smelter operation by Taracorp and lead reclamation activities conducted by SLLR. The IEPA procured Administrative Orders by Consent with Taracorp, SLLR, Stackorp, Inc., Tri-City Truck Plaza, Inc., and Trust 454 during March 1984. The orders required the implementation of remedial activities relative to air quality.

NL Industries, as former owner of the location, voluntarily entered into an Agreement and Administrative Order by Consent with United States Environmental Protection Agency (USEPA) and IEPA in May 1985 to implement a Remedial Investigation/Feasibility Study (RI/FS) for the location and other potentially affected areas. Taracorp was not a party to the agreement due to the fact it filed for bankruptcy. The USEPA determined the location was a Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) facility and it was placed on the National Priorities List on June 19, 1986.

1.2 DOCUMENT ORGANIZATION

This final project report is intended to provide a detailed description of the tasks involved in performing the work. Section 2.0 describes the scope of work involved in the preparation of the site-specific plans, performance of site administration/logistical support, mobilization/demobilization, site preparation/teardown, and the operational/technical scope of work performed. Section 2.0 also compares the actual scope of work performed with the planned scope of work in general terms. Section 3.0 describes the technical approaches implemented to accomplish the operational and technical tasks of the project including

sampling, analysis, waste transportation, and waste disposal. Section 4.0 describes the Health and Safety approaches implemented to accomplish the operational tasks of the project. Section 5.0 and 6.0 contain the quantity summary tables and verification analytical summary tables respectively. Appendix A depicts the Flow Charts showing work performance. Appendix B provides detailed descriptions of the work performed at each remedial location, as well as, tables and maps detailing the sampling and analysis. Appendix C contains the detailed descriptions of work performed on the easements for this project.

2.0 SCOPE OF WORK

The scope of work for this project was delineated by the documents USACE supplied to OHM entitled: Scope of Work for Contract DACA45-95-R-0015, Stack Emissions (Lead) Removal, Madison, Illinois.

The scope of work generally encompassed the following tasks:

- Preparation of site-specific plans
- Site administration and logistical support
- Mobilization and demobilization
- Site preparation and teardown
- Excavation, Backfill, and Compacting
- Turf
- Operational scope of work
- Waste transportation and disposal

2.1 PREPARATION OF SITE-SPECIFIC PLANS

OHM revised the site-specific project work plan (WP) from DO 17 to serve as a guideline describing how the work was to be performed in order to meet the requirements specified by USACE. The WP also included the chemical data acquisition plan (CDAP) and the location-specific health-and-safety plan (LSSHP).

Variances to the WP occurred during the project but were conducted only under authorization/direction of the USACE on-site representative(s). His/her purpose was to allow the project to function more efficiently while still remaining within all regulatory requirements. These variances are referenced and described in the relevant sections of this report.

The CDAP was prepared as a guideline to describe how, where, and how many samples would be collected. The laboratory analysis methods to be used, per the requirement of USACE's revised scope of services, were also outlined in the CDAP. In response to existing field conditions, this CDAP was amended to add the quality assurance project plan (QAPP) during the actual performance of work (see Section 2.6 for these amendments).

The LSSHP was prepared as a guideline describing the health and safety procedures which would be followed during the performance of the project. LSSHP addressed physical, chemical, and environmental hazards unique to this project site. This LSSHP was amended prior to the project to allow remedial work to

be performed by personnel wearing modified USEPA Level D personal protective equipment (PPE). The results of air monitoring indicated personnel could safely perform work at the remedial locations wearing poly tyvek suits, booties, gloves, hard hats, and safety glasses without respirators. Details pertaining to health and safety issues are discussed in Section 4.0, Health and Safety Summary.

2.2 SITE ADMINISTRATIONAL/LOGISTICAL SUPPORT

The project site administration was centrally located at # 10 Farrish in Madison, Illinois. Site administrative activities performed from this location included:

- Site Supervisor
- Cost tracking/reporting
- Health and Safety administration
- Waste tracking/documentation
- Field sampling/analytical support
- Field purchasing/subcontract management
- Logistical support

Prior to the physical work, logistical preparation activities were performed, including the following activities:

- Conduct a pre-construction meeting
- Verifying waste hauling licenses
- · Meeting with property owners
- · Locating utilities at necessary sites
- Establishing transportation routes
- Coordinating with local agencies and hospital

2.3 MOBILIZATION/DEMOBILIZATION

OHM performed mobilization of personnel and equipment primarily from its facility in O'Fallon, Missouri. A large percentage of the heavy equipment utilized on this project came from local vendors acting as subcontractors.

2.3.1 Subcontractors

Subcontractor activities were managed by the OHM project manager and site supervisor, and by USACE when necessary. Subcontractors were responsible for transportation, disposal, backfill material, sod and on-site equipment.

2.3.2 Permits

All necessary permits and licenses were secured before site mobilization. The transporter companies and disposal facilities were USEPA-licensed. Prior to mobilization, all on-site employees completed

Occupational Safety and Health Administration (OSHA) 40-hour hazardous material training.

2.4 MOBILIZATION/DEMOBILIZATION

Sites were set up and/or torn down at each remedial lot.

2.4.1 Command Center

The command center served as the central location from which all personnel were dispatched to their respective work locations each day or as needed. The command center was located inside of a secured building and was equipped with computers, copiers, facsimile machine, telephones, and base radio. The rear of the building also served as a storage area for OHM's equipment, tools, and materials.

2.4.2 Remedial Locations

Site preparation was performed at each of the remedial locations. OHM set up decontamination points for personnel and equipment and exclusion zones were established prior to excavation. These exclusion zones were identified with orange snow fencing and yellow caution tape across existing fencing. They remained in place until backfill had been completed to a sufficient depth.

Excavation equipment used on the site was decontaminated prior to demobilization or backfill. Gross contamination was scraped from the machines before they were washed. As a dust control measure, the decontamination rinse water was collected and applied to the last load of contaminated soil.

2.5 OPERATIONAL SCOPE OF WORK PERFORMED

The excavation activities involved the removal of contaminated soils from the remedial sites. Restoration involved backfilling, seeding, and sodding of the sites after completing the remedial activities. The scope of work for this portion of the project is illustrated in Figure 2.1.1 The operations Flow Chart is depicted in Appendix A-1.

OHM's schedule for excavation was developed to facilitate logistical management and limit the time required to transport equipment and crews from location to location. During excavation activities, engineering controls and security measures, such as surrounding the exclusion zones with fluorescent orange polyvinyl chloride (PVC) barrier fencing, were employed to prevent cross contamination and unauthorized entry into exclusion zones.

Each of the stack emission sites had unique characteristics, which mandated particular methodologies of remediation.

2.5.1 Pre-construction Activities

Pre-construction activities for this portion of the project included the following items:

2.0 SCOPE OF WORK

- Conducting a pre-construction meeting with USACE
- Issuing subcontracts
- Communication with Julie Corporation (the utilities' identification organization in Illinois) to locate potential underground utilities at the site
- Obtaining permits
- Obtaining soil samples for waste characterization
- Videotaping residential properties for restoration purposes

2.5.2 Construction Activities-Lots

The excavation techniques employed at each location varied according to location accessibility, depth, and extent of material. Minimization of disturbances to adjoining properties/areas was also a key consideration in performing each excavation. OHM used Bobcat mini-excavators, TL26, Takeuchi, TCM806 along with Kubota Tractors and manual removal methods.

Dust control was a major consideration. A storage system with pump and hose were available at all times to prevent fugitive emissions. Water trucks were also utilized to provide additional dust control and to transport water to sites for decontamination.

Most of the residential yards needed to have sod removed at varying depths of soil. Wastes were excavated using a track excavator, Takeuchi, and/or a Bobcat. At some locations, hand digging was necessary. Special soil was loaded into licensed waste hauler trucks for transportation to the disposal facility.

Most of the driveways contained aggregate soil mixtures. Most locations were accessible but required smaller equipment and hand digging. Non-hazardous waste (special waste) was classified analytically. The special waste was loaded into licensed haul trucks and sent to the disposal site.

2.5.4 Restoration

After excavation to predetermine depth had been achieved, OHM restored the location to preremedial conditions. Excavation areas were backfilled with clean soil and restoration was completed as required by the specifications. Sodding, seeding, and revegetation were performed when necessary.

2.5.5 Waste Removal

Wastes removed from the sites were transported to one of two locations. Milam RDF/Chain of Rocks. Figure A-2 in Appendix A shows the flow chart for T&D.

2.6 SAMPLING AND ANALYSIS

The following paragraphs detail the sampling and analysis tasks, as well as CDAP amendments/adjustments.

2.6.1 Sampling and Analysis Tasks

The sampling and analysis tasks for this project involved the following items:

- Street Sweeping
- Pre-characterization sampling and analysis of sites included as delineated by USACE
- Pre-characterization sampling and analysis of additional sites
- Resample (stack emission) as directed by USACE
- Backfill sampling

Street Sampling

OHM collected random grab samples from streets, as directed by USACE, for the purpose of determining the lead content of the street.

As per the scope of services issued to OHM by USACE, material at the residential sites exhibiting concentrations of total lead greater than 500 mg/kg were to be removed and disposed.

Samples were collected from one point in the front yard and one point in the back yard. Both samples collected were at least 10 feet from any structures if possible.

Site Pre-Characterization Sampling and Analysis

As the project progressed, the need to establish the level of effort anticipated for each upcoming site became much more apparent. The need to pre-characterize each of the remedial locations to establish reasonable estimates of non-hazardous waste requiring removal was made evident via an amendment to the CDAP. The site pre-characterization sampling and analysis efforts were applied to non-hazardous (stack emission) sites. The primary purpose of these efforts was to confirm or refute the potential contamination at each remedial location and to obtain an indication of the extent of contamination at sites with lead concentrations greater than 500 mg/kg. The most efficient and productive approaches to the pre-characterization sampling and analysis, which include the steps described in the following paragraphs, were ultimately developed for the residential lots.

Pre-characterization sampling and analysis at the residential lots included the establishment of two sample locations at each site. The two sample points were positioned at the center of the front and back yard of each location. One sample was then collected at the following depths from each sample location: 0 to 3 inches, 3 to 6 inches, and 6 to 12 inches.

The laboratory analysis of the samples followed the logic as below. The two samples representing the top 3-inch layer of each of the locations were analyzed for total lead and toxicity characteristic leaching

procedure (TCLP) lead. The second and third set (representing 3 to 6 and 6 to 12 inch depths) were analyzed for total lead only.

This is depicted in Figure A-3 in Appendix A.

Pre-characterization of Additional Sites

Under authorization of USACE, OHM performed the pre-characterization sampling of additional sites over and above the original scope of services. The objective of this was to determine the potential presence of lead contamination with anticipation for the planning of remediation at these same sites. The technical approach for this task involved the same approaches as mentioned in the preceding paragraphs concerning pre-characterization.

2.6.2 CDAP Amendment/Adjustments

Development of the Sampling for Backfill Material

An amendment for the sampling and analysis of backfill was designed to show that incoming backfill material was clean to USEPA standards. This was done as a composite sample on every 1000 cubic yards of backfill and run for the following analysis:

- TCLP for Cd, Cr, Pb
- PAH-IEPA Levels
- Pesticides/PCB's
- TPH
- GRO
- DRO
- Total VOC's

2.7 TRANSPORTATION AND DISPOSAL

The transportation and disposal (T&D) of waste from the sites included the shipment of non-hazardous waste shipped to the Chain of Rocks facility/Milam facility. The special waste was transported by Garcia Trucking. The transportation of the waste was performed with tandem dump trucks.

2.7.1 Transportation of Waste

Each site was identified by an address which was written on the manifest. The site was then assigned a 5-digit manifest document number at the time of shipment. This system ensured the trucks origin was documented.

The State of Illinois requires each special waste shipment be on an all Illinois manifest. This allowed each shipment of special waste to also be cross-referenced with the preprinted Illinois manifest document.

2.7.2 Disposal of Wastes

This project involved the removal and disposal of special non-hazardous industrial waste (non-hazardous waste) which was primarily removed from residential locations. The objective of the non-hazardous waste excavation efforts was to remove all material exhibiting concentration of total lead above 500 mg/kg, but less than 5 mg/l, when analyzed by TCLP.

Disposal characterization of waste was determined by analyzing composite samples, as directed in Section 2.6. Pre-characterization analysis was done at each site to verify depth of lead contamination. The characterization of certain waste as non-hazardous was confirmed at each site with the performance of TCLP lead analysis of composite samples.

The disposal facility subcontracted to provide non-hazardous waste disposal was the Chain of Rocks facility/Milam. OHM obtained the approved waste profile by providing analytical that was previously performed under the Rapid Response Contract.

3.0 TECHNICAL APPROACH

The stated objective of this project was to excavate and dispose of lead contaminated soil in yards of residential communities as per the Record of Decision between the USEPA, IEPA, and the potentially responsible parties (PRPs) for the Superfund site.

This section describes the general approach implemented to complete the work in the residential lots. The methods implemented to perform the work on this project fall into one category:

• Residential lots (Non-Hazardous)

The operational effort extended was supported by the technical information that was gained through implementation of the following:

- CDAP amendment/adjustment
- Transportation and disposal, Appendix A-2

3.1 PRE-CONSTRUCTION ACTIVITIES

The pre-construction activities performed during this project were predominantly associated with obtaining disposal permits; obtaining transportation permits; preparing and delivering notifications of work to the public; attending public meetings; and identifying utilities at each remedial location. Many of these pre-construction activities were performed on an on-going basis as the project proceeded from one remedial location to the next.

The permits for the disposal of non-hazardous waste were obtained prior to shipment of the waste.

Before work progressed from one remedial location to the next, the identification of utilities was coordinated from the command center by OHM's safety supervisor. The identification of the utilities was coordinated with Julie Corporation. OHM's safety supervisor would telephone Julie Corporation and notify the organization of OHM's intention to perform work at a given site. Julie Corporation would then issue a "dig number" to OHM and notify all utility companies listed to provide service for the area of concern. Typically, the utility companies would mark the utilities on the site within 48 hours of OHM's initial contact with Julie Corporation.

OHM's subcontractors who performed the transportation of waste and equipment at and through the cities of Madison, Venice, and Granite City, Illinois City obtained required transportation permits.

3.2 SAMPLING AND ANALYSIS

The sampling and analysis tasks involved the following items:

- Laboratory confirmation sampling and analysis
- Pre-characterization sampling and analysis
- Backfill sampling

As per the direction of USACE, material at the residential sites exhibiting concentrations of total lead greater that 500 mg/kg were removed and disposed.

3.2.1 Pre-Characterization Sampling and Analysis

As the project progressed, the need to establish the level of effort anticipated for each upcoming site became much more apparent. The need to pre-characterize each of the remedial locations for establishing reasonable estimates of non-hazardous waste requiring removal was made evident through incorporation into the CDAP. The site pre-characterization sampling and analysis efforts were applied to non-hazardous (stack emission) sites. The primary purpose of the pre-characterization sampling was to confirm presence of non-hazardous waste meeting the action level. The most effective and productive approaches to the pre-characterization sampling and analysis were ultimately developed for the residential lots.

3.2.2 Technical Approach to Stack Emission Lots

The technical approach to the stack emission lots differed from the residential battery casing cleanups in the respect no confirmation sampling was necessary. The reason for this was due to previous sampling results yielding a pre-determined depth per USEPA. Consequently, yards were excavated to this pre-determined depth. In addition, all waste was shipped out as special-direct to a landfill.

3.3 CHEMICAL DATA ACQUISITION PLAN AMENDMENTS/ADJUSTMENTS

3.3.1 Development of the Sampling for Backfill Material

An amendment for the sampling and analysis of backfill material was designed to show that incoming backfill material was clean to USEPA standards. This was done as composite samples on every 1000 cubic feet of backfill and run for the following analysis:

- TCLP for Cd, Cr, Pb
- PAH-IEPA Levels
- Pesticides/PCB's
- TPH
- GRO
- DRO
- Total VOC's

3.4 TRANSPORTATION AND DISPOSAL

The T & D of waste removed from the sites included the shipment of non-hazardous waste by Garcia Trucking to Chain of Rocks Landfill/ Milam in Granite City, IL.

3.3.1 Transportation of Waste

Each site was identified by an address, which was written on the manifest. The site was then assigned a 5-digit manifest document number at the time of shipment. This system ensured the trucks origins were documented.

3.3.2 Disposal of Wastes

Disposal characterization of the waste was determined by analyzing composite samples, as described in Section 2.6. Verification of waste characterization was performed at each site through pre-characterization efforts. The characterization of certain waste as non-hazardous was confirmed at each site with the performance of total lead and TCLP lead analysis of composite samples.

The disposal facility subcontracted to provide non-hazardous waste disposal was Chain of Rocks/Milam in Granite City, IL. OHM obtained the approved waste profile by providing analytical that was previously done under Rapid Response Contract.

4.0 HEALTH AND SAFETY SUMMARY

4.1 PROJECT SUMMARY AND CONCLUSIONS

4.1.1 **Summary**

The following summarizes the health and safety aspects of this project:

- Task-specific hazard evaluations were performed each day at each work site prior to the start of work
- Air monitoring data was used during this project to verify appropriate personal protection was being used for site conditions. Personnel medical monitoring was performed prior to and at the end of the project to determine lead levels in the blood.
- Perimeter samples indicated total lead concentration below the action limit established in the LSSHP. Although results obtained are "after the fact," no personnel or citizens were at risk to exposure at any time.
- Personnel air sampling data indicated no detectable reading for total lead. There were no recorded cases of personnel overexposure to ambient lead levels.

4.1.2 Conclusions

Following completion of the project, the OHM Health and Safety Department made the following conclusions:

- The LSSHP was effectively implemented to address the health and safety hazards associated with each phase of site operations and to meet the requirements set forth in 29 CFR 1910.120.
- The existing LSSHP is appropriate for future phases of work at this site involving the same work activities.
- Future work should be performed in Level D PPE with appropriate air monitoring to verify the selection of PPE. An action level of 30mg/m3 should be used to warrant controls. Once monitoring shows consistent reading below the action level, the amount and frequency of air monitoring may be appropriately limited/reduced.
- Special attention should be paid to prevent any recordable accidents and near misses during the course of future work. Routine tasks should be reviewed and evaluated for potential hazards.

4.2 SITE SAFETY AND HEALTH PLAN EVALUATION

A LSSHP was issued before the start of this project to address the health and safety hazards

associated with each phase of site operations. The plan met the requirements of 29 CFR 1910.120. The phases of work addressed in the LSSHP include the following:

- Mobilization
- Installation of perimeter fence
- Soil sampling
- Excavation of contaminated soil
- Load-out of contaminated soil
- Backfill of excavation
- Restoration of disturbed areas
- Decontamination and demobilization

4.2.1 Provisions

Once on site, waste materials were designated to be directly loaded into dump trucks.

Provisions were made to address heavy equipment, excavation and other physical hazards. Hazards associated with vehicle and pedestrian traffic in work areas and roadways were controlled by the use of warning signs, Men at Work signs, and road guards to direct traffic.

4.2.2 Personal Protective Equipment

PPE visions were made to minimize exposure to lead contamination for personnel on site. Level D PPE included the following:

- Hard hat
- Safety glasses
- Steel-toed leather safety shoes/boots
- Poly tyvek coveralls
- Nylon booties (under) and Robar/Tingley boots (outer)
- Inner sample gloves, outer cloth or leather gloves

An action level of 15.0 mg/m3 of airborne lead, as determined by integrated sampling, was set by USACE to upgrade the level of PPE to Level C (including use of an air purifying respirator.) Air monitoring was performed for the duration of remedial activities to ensure proper PPE use.

4.3 SITE SAFETY

4.3.1 Accidents

Employee safety was OHM's first priority. After performing more than 157,454 man hours on this project, OHM personnel suffered no OSHA-recordable accidents or injures.

4.3.2 Preventative Measures

A number of measures were taken on site to prevent accidents and injures. Daily safety meeting were held to discuss: hazards associated with upcoming work tasks; the use of specific tools and equipment; and other chemical, physical, and environmental hazards associated with site work. Task-specific hazard evaluations were performed each day at the work sites prior to the start of work.

Controls were used to eliminate the hazards associated with vehicle and pedestrian traffic near the work locations. Warning signs were posted and guards were used to direct traffic.

A heat stress prevention program was also instituted on site. Personnel heat stress monitoring was performed to prevent heat related illnesses during work in high ambient temperatures. Site workers= pulses, body temperatures, and blood pressures were taken before and after each break. Work-rest schedules were determined by the results of this monitoring in accordance with the LSSHP heat stress monitoring criteria.

Specific work/rest regimens were established at the start of every work day based on the specific work conditions for that day (temperatures, time of day, amount of sun or shade, etc.) Breaks were taken in shady areas as designated throughout the work shift. Personnel removed PPE and were given cool liquids to drink (e.g., juice, water). Visual observation by a designated safety official was used to identify individuals exhibiting symptoms of heat-related illness and to take the necessary actions.

4.4 EXPOSURE MONITORING

4.4.1 Methodology

Air monitoring was performed to determine the ambient levels of total suspended particulates generated during excavation and to determine total ambient lead exposure for site personnel and perimeter emissions. At the start of each work day, wind direction was used to determine the placement of sampling instruments on site.

Personnel and perimeter samples were taken to determine the levels of total lead in the air of the personal breathing zone and at the site perimeter. Lead samples were collected and analyzed using NIOSH Method 7300 and battery-operated air sampling pumps (Gillian or equivalent) fitted with 37-millimeter (mm) mixed cellulose ester (MCE) filters (0.8-micron pore diameter).

4.4.2 Perimeter Sampling

Three perimeter samples were taken daily over the course of the work shift. One sample was taken upwind of site operations and two were taken downwind. Perimeter samples were taken above ground levels (approximately 4 to 5 feet in height) to characterize the breathing zone and to prevent contamination due to foot traffic. The pump flowrate was calibrated and set at approximately 20 liters per minute for the duration of the task (about 8 hours.)

Samples were assigned identification numbers based on an established code. The analytical laboratory used was Environmetrics, 11401 Moog Drive, St. Louis, Missouri. Standard turnaround time for

sample results was 24 to 48 hours by facsimile; original data was then returned by mail.

4.4.3 Personnel Sampling

Personnel air samples for lead were taken for a respective number of employees performing intrusive activities within the exclusion zone (one employee from each job category; at least two employees per day per site). The samples were taken in the person's breathing zone for the duration of the day's shift. Samples were collected at the end of the work day and sent to the analytical laboratory for analysis of total lead. A blank sample was included in shipment.

4.4.4 Medical Monitoring

Personnel blood lead levels were determined prior to and after the completion of work for this project.

5.0 QUANTITY SUMMARY TABLE

Quantities of material were tracked for each lot or site remediated. Table 5.1 presents a summary of these totals.

DACA45-96-D-0014 D.O. 0005 Project 19531

QUANTITY SUMMARIES

Site	Special	Sod	CA-6	CA-7	Topsoil	Backfill
Address	cu yd	sq yd	ton	ton	cu yd	loads
1920 Adams	119.37	960	46.2	28.84	119.37	
1924 Adams	89.12	420	44.75	14.6	14.75	6
1928 Adams	89.12	420	44.75	14.6	14.75	6
2034 Adams	301.42	1260			46.15	35
2100 Adams	319.25	840	54.8	26.7	79.98	15
2108/10 Adams	36.35	240	14.65		20.54	
2114 Adams	77.70	600	57.95		41.06	5
2116 Adams	146.82	360	13.79	28.35	104.41	26
2120/22 Adams	103.31	420			70.03	8
2132/34 Adams	86.65	300	56.48	14.27	34.48	7
2144/46 Adams	137.88	360	40.55	26.95	23.37	10
2148 Adams	146.62	270	86.9	28.5	26.66	3
2156 Adams	106.55	240	30.05	28.4	13.71	8
2158 Adams	60.29	180			25.32	6
2160 Adams	100.40	240	39.6			8
1022 Alton	152.97	480	72.35	21.98	47.22	10
1026 Alton	124.53	420	42.3	21.63	33.35	5
1911 Benton	50.78	180	12.8	14.07	40.45	
1915/17 Benton	64.76	210	14.65	14.3	31.48	5
1916 Benton	35.76	150	29.65	31	23.08	1
1919/21 Benton	63.92	180	31.15	44.8	39.22	
1920 Benton	25.14	120		14.9	21.54	
1922 Benton	26.25	120		14.8	9.23	
1923 Benton	60.64		32.55	46.7		
1924 Benton	46.68	120	16.45	16.6	12.31	2
1925/27 Benton	32.00	452			49.03	
1926 Benton	33.64	150	17.5		11.34	
1928 Benton	51.28	240	26.3	14.6	27.72	1
1930 Benton	50.85	240	42.09		59.40	2
1932 Benton	37.82	240		15.45	34.95	
1934 Benton	30.82	180			34.08	
1936 Benton	58.43	300	29.05	16.7	12.01	3

		/			
8.02	360	27.65	29.6	18.35	4
34.24	360			59.38	
23.18	120		28.9	47.48	
23.18	120		18.9	47.48	
60.92	510			57.16	
47.88	300		28.3	45.77	
80.47	210	44.7	14.7	45.79	1
47.39	240	43.55		12.02	2
117.20	360	29.7	13.6	40.16	8
118.31	420			57.21	8
30.50	120	13.45	14.1	10.78	2
94.02	240			11.93	1
72.66	420			57.18	
47.75	180			12.31	
29.89	180		15.3		3
123.86	660	76.59		52.57	6
32.16	150		17.55		
39.55	150	74.45	16.25		
127.22	180	28.35		69.39	10
126.71	444	29.3	14.5	116.52	3
57.18	317	14.35	13.95	48.67	2
96.49	378		13.5	24.52	6
64.65	444.5	14.8		57.59	3
42.25	190.5			23.35	
229.48	540	76.55	25.35	83.12	5
82.88	240	44.4	14.6	32.31	6
46.77	360			45.27	
42.31	360	30.5	27.1		4
49.51	300		14.5		5
30.78	60		30.4	13.33	
33.17	420	14.55	14.65	23.65	
31.80	120			23.08	
68.25	180	16.15	12.85		4
46.71	240	14.77	13.8	24.03	2
94.72	180	14.65	44.5	47.69	3
107.87	189	90.05	27.46	21.08	5
145.12	300		55.35	125.38	8
118.38	240	45.33	25.55	54.68	2
	34.24 23.18 23.18 60.92 47.88 80.47 47.39 117.20 118.31 30.50 94.02 72.66 47.75 29.89 123.86 32.16 39.55 127.22 126.71 57.18 96.49 64.65 42.25 229.48 82.88 46.77 42.31 49.51 30.78 33.17 31.80 68.25 46.71 94.72 107.87 145.12	34.24 360 23.18 120 60.92 510 47.88 300 80.47 210 47.39 240 117.20 360 118.31 420 30.50 120 94.02 240 72.66 420 47.75 180 29.89 180 123.86 660 32.16 150 39.55 150 127.22 180 126.71 444 57.18 317 96.49 378 64.65 444.5 42.25 190.5 229.48 540 82.88 240 46.77 360 42.31 360 49.51 300 30.78 60 33.17 420 31.80 120 68.25 180 46.71 240 94.72 180 107.87 189 <td< td=""><td>34.24 360 23.18 120 60.92 510 47.88 300 80.47 210 44.7 47.39 240 43.55 117.20 360 29.7 118.31 420 30.50 120 13.45 94.02 240 72.66 420 47.75 180 29.89 180 123.86 660 76.59 32.16 150 39.55 150 74.45 127.22 180 28.35 126.71 444 29.3 57.18 317 14.35 96.49 378 64.65 444.5 14.8 42.25 190.5 229.48 540 76.55 82.88 240 44.4 46.77 360 30.5 49.51 300 30.5 49.51 300 30.78 60 33.17 420 14.55 31.80 120 68.25 180 16.15 46.71 240 14.77 94.72 180 14.65 107.87 189 90.05 145.12 300 30.05 145.12 300 <t< td=""><td>34.24 360 23.18 120 28.9 23.18 120 18.9 60.92 510 28.3 47.88 300 28.3 80.47 210 44.7 14.7 47.39 240 43.55 117.20 360 29.7 13.6 118.31 420 30.50 120 13.45 14.1 94.02 240 72.66 420 47.75 180 15.3 29.89 180 15.3 123.86 660 76.59 32.16 150 74.45 16.25 127.22 180 28.35 126.71 444 29.3 14.5 57.18 317 14.35 13.95 96.49 378 13.5 64.65 444.5 14.8 42.25 190.5 229.48 540 76.55 25.35 82.88 240 44.4 14.6 46.77 360 30.5 27.1 49.51 300 30.5 27.1 49.51 300 14.55 14.65 31.80 120 68.25 180 16.15 12.85</td><td>34.24 360 28.9 47.48 23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 12.31 29.89 180 15.3 12.31 12.31 29.89 180 15.3 12.31 29.89 180 15.3 52.57 32.16 150 37.45 16.25 69.39 126.71 444 29.3 14.5 116.52 57.18 31.5 14.5 116.52 57.18 31.5 24.52 64.65 444.5 14.8 57.59</td></t<></td></td<>	34.24 360 23.18 120 60.92 510 47.88 300 80.47 210 44.7 47.39 240 43.55 117.20 360 29.7 118.31 420 30.50 120 13.45 94.02 240 72.66 420 47.75 180 29.89 180 123.86 660 76.59 32.16 150 39.55 150 74.45 127.22 180 28.35 126.71 444 29.3 57.18 317 14.35 96.49 378 64.65 444.5 14.8 42.25 190.5 229.48 540 76.55 82.88 240 44.4 46.77 360 30.5 49.51 300 30.5 49.51 300 30.78 60 33.17 420 14.55 31.80 120 68.25 180 16.15 46.71 240 14.77 94.72 180 14.65 107.87 189 90.05 145.12 300 30.05 145.12 300 <t< td=""><td>34.24 360 23.18 120 28.9 23.18 120 18.9 60.92 510 28.3 47.88 300 28.3 80.47 210 44.7 14.7 47.39 240 43.55 117.20 360 29.7 13.6 118.31 420 30.50 120 13.45 14.1 94.02 240 72.66 420 47.75 180 15.3 29.89 180 15.3 123.86 660 76.59 32.16 150 74.45 16.25 127.22 180 28.35 126.71 444 29.3 14.5 57.18 317 14.35 13.95 96.49 378 13.5 64.65 444.5 14.8 42.25 190.5 229.48 540 76.55 25.35 82.88 240 44.4 14.6 46.77 360 30.5 27.1 49.51 300 30.5 27.1 49.51 300 14.55 14.65 31.80 120 68.25 180 16.15 12.85</td><td>34.24 360 28.9 47.48 23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 12.31 29.89 180 15.3 12.31 12.31 29.89 180 15.3 12.31 29.89 180 15.3 52.57 32.16 150 37.45 16.25 69.39 126.71 444 29.3 14.5 116.52 57.18 31.5 14.5 116.52 57.18 31.5 24.52 64.65 444.5 14.8 57.59</td></t<>	34.24 360 23.18 120 28.9 23.18 120 18.9 60.92 510 28.3 47.88 300 28.3 80.47 210 44.7 14.7 47.39 240 43.55 117.20 360 29.7 13.6 118.31 420 30.50 120 13.45 14.1 94.02 240 72.66 420 47.75 180 15.3 29.89 180 15.3 123.86 660 76.59 32.16 150 74.45 16.25 127.22 180 28.35 126.71 444 29.3 14.5 57.18 317 14.35 13.95 96.49 378 13.5 64.65 444.5 14.8 42.25 190.5 229.48 540 76.55 25.35 82.88 240 44.4 14.6 46.77 360 30.5 27.1 49.51 300 30.5 27.1 49.51 300 14.55 14.65 31.80 120 68.25 180 16.15 12.85	34.24 360 28.9 47.48 23.18 120 18.9 47.48 60.92 510 57.16 47.88 300 28.3 45.77 80.47 210 44.7 14.7 45.79 47.39 240 43.55 12.02 117.20 360 29.7 13.6 40.16 118.31 420 57.21 30.50 120 13.45 14.1 10.78 94.02 240 13.45 14.1 10.78 94.02 240 11.93 72.66 420 57.18 12.31 29.89 180 15.3 12.31 12.31 29.89 180 15.3 12.31 29.89 180 15.3 52.57 32.16 150 37.45 16.25 69.39 126.71 444 29.3 14.5 116.52 57.18 31.5 14.5 116.52 57.18 31.5 24.52 64.65 444.5 14.8 57.59

2037 Bryan	138.04	508	30.55		82.58	11
2103 Bryan	159.33	420	58.9	90.5	24.82	8
1715 Chestnut	137.65	283.5	73.09	14.7	36.73	5
1718/20 Chestnut	161.02	120	16,98	34.77	54.33	9
1723 Chestnut	218.25	1200	28.15	14.7	74.95	16
1753 Chestnut	181.56	477	149.3	13.95	36.55	9
1929 Cleveland	126.25	189	83.9	29.15	49.86	1
1935 Cleveland	75.35	240	27.3		40.77	4
1939 Cleveland	122.98	510			32.91	6
2006 Cleveland	89.48	300		12.85	36.55	7
2026 Cleveland	75.70	420		15.05	33.89	5
2028 Cleveland	111.78	420	15.9		23.07	6
2029 Cleveland	96.57	480	14.75		83.78	2
2055 Cleveland	47.63	320			39.07	
2057 Cleveland	66.82	420	35.44		51.50	
2056/58 Cleveland	46.37	180		12.32		3
2100 Cleveland	123.05	180	34.27	19.11	42.60	5
2110 Cleveland	69.46	540				11
2114 Cleveland	70.94	360				4
2116 Cleveland	178.88	900		14.9	92.42	11
2107/17 Cleveland	104.49	420	21.82	13.5	21.72	7
2119 Cleveland	65.64	180			10.98	5
2121 Cleveland	110.88	126	73.8	13.6		1
2127 Cleveland	37.51	252			28.33	1
2133 Cleveland	38.96	300			36.46	
2137/39 Cleveland	60.79	190.5	59.2	15.5	33.92	
2140 Cleveland	126.12	420	15.15	29.8	23.07	3
2142 Cleveland	85.12	180	46.75		24.62	5
2145 Cleveland	51.30	381			34.41	3
2149 Cleveland	95.55	240	54.3	20.15	21.85	3
2153 Cleveland	71.80	317.5	13.75		32.95	3
2156 Cleveland	86.38	635			34.49	6
2158 Cleveland	87.18	300			10.92	3
2160 Cleveland	83.60	190.5	73.65	14.05	30.28	5
2161/63 Cleveland	37.95	318	15	15	13.73	2
2167 Cleveland	74.04	572			69.44	· · · · · · · · · · · · · · · · · · ·
2200 Cleveland	243.87	120	220.4			11
2201 Cleveland	81.54	350			34.68	

2205 Cleveland	35.94	180		13.95		2
2209/11 Cleveland	57.38	420	15.1	15.2	57.55	
2214 Cleveland	55.72	254	14.45	15.2	24.78	2
2217 Cleveland	95.18	300			60.26	3
2218 Cleveland	55.68	286			47.23	
2221 Cleveland	63.88	390	30.15		11.22	2
2222 Cleveland	58.39	480	32.15		34.92	
2225 Cleveland	193.93	480	59.26	15	79.39	5
2226 Cleveland	119.75	390			76.59	9
2229 Cleveland	152.95	480	83.45		20.11	11
2234 Cleveland	53.84	317.5	16.7	15.2	36.61	
2237 Cleveland	300.91	780	70.05	13.25	56.48	15
2238 Cleveland	101.58	480	30.9	12.91	30.00	14
2246 Cleveland	45.35	254			33.11	2
2258 Cleveland	45.36	444.5			46.15	
1812/14 Delmar	83.99	180	14.05		11.03	4
2015/17 Delmar	40.63	240			9.45	2
2019 Delmar	40.25	300			45.34	1
2025 Delmar	27.35	317.5	14.95	14.3	22.42	
2033 Delmar	32.23	240		13.7	11.25	1
2116/18 Delmar	42.20	100	72.55			3
2120 Delmar	99.85	700	53.25			18
2121 Delmar	49.70	300	29.73			7
2125/27 Delmar	43.59	240	29.1			1
2129 Delmar	66.32	300	29.58	15.27		7
2130 Delmar	111.37	420	74.65	14.85		13
2133/35 Delmar	65.72	240	15.45	14.8	34.94	1
2134 Delmar	114.41	360				15
2137/39 Delmar	121.91	210	61.4	27	36.59	6
2138 Delmar	79.15	240	17.3		40.39	6
2141/43 Delmar	48.85	350	12.55	29.35	12.37	2
2146 Delmar	60.02	434				8
2147 Delmar	89.81	420	13.5	31.39	56.57	5
2149 Delmar	63.29	600			35.75	1
2150 Delmar	75.15	420	15.8			8
2154/56 Delmar	64.45	240	15	15.05		6
2200 Delmar	69.78	480	27.86			8
2201 Delmar	92.55	540	15.65	14.85	56.27	3

(

2205 Delmar	89.67	300	29.65	14.5	29.88	4
2206 Delmar	33.65	240	15	15.05		3
2210 Delmar	108.07	500	43.77			11
2215 Delmar	46.90	300	43.77		34.42	1
2219 Delmar	111.87	550	15.85	15.1		12
2234 Delmar	42.39	420	12.48	14.56	19.35	2
2237/39 Delmar	39.81	190.5	15.6		31.68	
2238 Delmar	50.92	360	15.45	15.35	6.15	14
2243 Delmar	88.24	222.5	44.8	14.9	47.82	2
2246 Delmar	112.90	360	14.33			11
2247 Delmar	23.24	120		14.3	13.19	1
2252 Delmar	115.13	360	28.95			8
2253 Delmar	52.01	180	23.87		21.55	2
2258 Delmar	47.19	240	14.7			6
2259 Delmar	53.58	120				5
2262 Delmar	51.81	360	14.35		23.27	2
2503 Denver	124.67	120	13.9	13.7	51.68	9
2505 Denver	82.06	320	29.75		11.58	6
2507 Denver	64.86	222.5		15.4	12.82	4
2118 Edison	107.93	180	148.05	31.4		4
2121 Edison	88.75	120	88.1	14.15		2
2122 Edison	63.72	480				10
2123/25 Edison	25.51	240	13.9	13.2	18.15	3
2124 Edison	104.69	180	86.74	13.52		4
2128/30 Edison	46.75	180	15.37	13.25		4
2132 Edison	60.65	180	29.85	14.75		3
2137/39 Edison	53.23	240	26.85	14.15		6
2138 Edison	64.19	420			23.08	5
2141/43 Edison	53.82	378	53.2	16		5
2153 Edison	55.10	330	14.1			4
2154 Edison	50.93	260	34.6			3
2204 Edison	102.15	240	15.55		9.17	8
	96.55	360	59.45	14.55	12.25	5
2211 Edison	76.68	480	30.95		11.55	6
2215 Edison	69.27	240	15.1		12.42	3
		480		13.45		8
	91.91	300		30.6	35.52	6
2236 Edison	102.46	480	29.6	13.8		6
2141/43 Edison 2153 Edison 2154 Edison 2204 Edison 2207 Edison 2211 Edison 2215 Edison 2219 Edison 2235 Edison	53.82 55.10 50.93 102.15 96.55 76.68 69.27 79.23 91.91	378 330 260 240 360 480 240 480 300	14.1 34.6 15.55 59.45 30.95 15.1 27.55	14.55 13.45 30.6	9.17 12.25 11.55	5 4 3 8 5 6 3 8

2237 Edison	28.78	120	 	14.35	T	2
2240 Edison	74.24	360	38.35	14.55		5
2246 Edison	89.37	420	12.65	17		7
2250 Edison	65.76	378	41.95	12.95		6
2251 Edison	49.47	300	58.41	12.30	11.07	2
2262 Edison	48.89	300	26.5	14.4	11.07	5
1871 Edwardsville	127.06	400	20.5	13.75	20.05	14
1703 Elizabeth	131.88	360		13.75	34.04	10
1703 Elizabeth	74.92	360	14.95	13.73	22.12	5
1920 Elizabeth	48.71	180	14.55		23.01	4
811 Grand	94.38	360		14.85	34.42	 7
825 Grand	40.04	120	13.3	14.00	34.42	3
		<u> </u>		20.3	23.54	
906 Grand	67.95	180	15.35	29.3	<u> </u>	4
907/15 Grand	284.94	1260	14.8	15.05	41.72	39
914 Grand	52.79	300	43.6	26.5	24.12	6
916 Grand	41.22	180	<u> </u>	<u> </u>	24.63	3
921 Grand	34.84	240			26.86	4
923 Grand	53.38	240			21.90	2
1000 Grand	20.99	210			11.37	2
1012 Grand	131.53	450	59.3	14.9	11.69	11
1013/19 Grand	189.40	952.5			56.76	17
1020 Grand	118.01	540			58.17	11
1021 Grand	26.88	127		15.1	12.08	2
1100 Grand	29.47	254			38.12	5
1101 Grand	194.72	347	74.55	14.9	83.48	8
1102 Grand	75.55	120		13.9	26.52	5
1105 Grand	117.64	317.5	43.95	14.45	37.14	8
1107 Grand	47.32	159		14.95	11.79	4
1108 Grand	92.17	300	11.95	14.65	25.32	6
1115 Grand	96.50	635			104.62	9
1125 Grand	48.63	254			25.04	6
1222 Grand	35.73	441		13.5	40.00	
1224 Grand	26.59	127		14.25	23.64	1
1233 Grand	335.79	1323		43.4	183.03	29
1240/42 Grand	204.97	850.5		28.45	271.45	16
1300 Grand	79.72	220.5	13.95	13.95	23.74	4
1303 Grand	98.74	346.5	40.8	1	23.74	7
1307 Grand	83.47	381	 	49.75	38.37	

67 15 381 31.9 49 43 1309 Grand 3 68 54 28 75 54 18 3 1311 Grand 360 540 13.2 38 74 10 1317 Grand 100 05 157.5 29.5 22.69 35.78 1323 Grand 1325 Grand 16.62 60 14 95 1 30 358 75 11.54 1330/32 Grand 189 72 10.92 11 91 1413 Grand 58 58 180 4 180 1417 Grand 45.90 4 27 23 2 1427 Grand 63 10.92 945 17 1447 Grand 249.69 14.69 58 66 93.35 444 5 148 10 1728/30 Grand 122 98 36 62 5 1734 Grand 140 36 1905 153 2 14 41 28 74.90 300 11.62 4 1918/20 Grand 16.38 1924 Grand 47.22 180 164 13.85 423 3 41.24 15.15 12 12 1928 Grand 1932/34 Grand 43.28 164 30 15 45.65 11.05 73.4 9.23 2 1933/35 Grand 150.12 63 104.97 60 15.25 2117/19 Grand 80.42 30.25 360 71.85 96.57 9 2129 Grand 101.93 704 13.1 2139 Grand 180 2149 Grand 91.05 420 8 2206 Grand 36.39 180 41.7 2 48.75 480 43.8 16.9 2208/10 Grand 6 72.50 310 60.85 14.2 5 2216/18 Grand 27.65 2224/26 Grand 130.37 300 13.6 6 2228 Grand 49.62 180 43.45 13.85 360 2240/42 Grand 50.88 29.2 14.2 3 300 2246 Grand 64.99 160.73 1140 14.6 108.32 21 928 Greenwood 420 23.95 38.48 1009 Greenwood 78.13 13.4 1012 Greenwood 152.45 660 61.7 51.8 54 86 8 28.13 1014 Greenwood 58.76 180 15.3 38.93 1016 Greenwood 50.95 180 5 88.62 540 44.89 1019 Greenwood 8 33.78 5 71.04 300 1022 Greenwood 41.85 180 6 1024 Greenwood 59.79 300 22.50 1028 Greenwood 14.1 4 1030 Greenwood 86.11 120 28.1 14.2 9

1022 Croppused	28.82	240	13.1	T	19.54	T
1032 Greenwood	163.05	315	13.1	29.1	19.54	13
1100 Greenwood 1102/04 Greenwood	102.63	420	29.05	14.35	22.30	6
1108 Greenwood	97.19	300	73.21	14.35	58.01	3
	43.35	420	73.21	 	24.51	2
1112 Greenwood			117.02	21.4		
1120 Greenwood	161.67	360	117.03	31.4	10.23	10
1133 Greenwood	156.80	900	4450	15.2	55.06	14
817 Iowa	42.13	240	14.59	13.1		3
819 Iowa	19.45	120	00.0	42.25	40.70	2
820 lowa	86.93	240	82.9	13.35	16.79	1
822 Iowa	52.71	240	 	31.7	23.58	1
825 Iowa	51.62	360	29.41			5
911 lowa	25.63	180		10.05		3
915/17 lowa	92.32	360		12.85	67.65	3
916 lowa	191.80	1200	28.15			24
922 Iowa	149.15	420		14.1	13.91	13
925 Iowa	83.22	700		7.5		9
1004/06 Iowa	44.87	180	58.05	12.85	10.71	2
1008 lowa	137.43	81	91.66		21.59	6
1013 lowa	58.39	240			24.02	4
1015 lowa	64.87	300				7
1030 lowa	114.18	600			18.84	12
1109 lowa	145.75	900	25.35		21.54	10
1115 lowa	120.40	300	13.2		33.65	14
1117 lowa	155.65	420	70.24	30.22		14
1124 lowa	275.60	780		15.45		30
1201 lowa	62.92	540	13.45	13.8	47.42	8
1205 lowa	41.16	300	13.9			5
1211 lowa	65.94	480			22.48	4
1213 lowa	95.61	300	44.85	15.3	22.34	6
1227 Iowa	102.88	506				12
1230 lowa	97.34	667	14.5	13.55	66.88	3
1231 Iowa	62.47	120	29.9	15.3	16.25	2
1245 Iowa	113.52	480		14.75	40.36	9
1301 lowa	130.02	600			56.28	10
1304 Iowa	30.42	32	29.5	14.8	12.08	
1305 lowa	77.97	60	44.5		9.35	2
1311 Iowa	52.60	360			23.02	4

(

1			Í			
1313 lowa	92.53	600	16.05		52.23	6
1316 lowa	89.72	360		15.6	39.56	4
1322 lowa	44.10	480			37.34	3
1324 lowa	70.72	360		14.25	49.45	2
1400 lowa	83.67	540	14.65	13.25	21.85	6
1406 Iowa	163.90	157.5	57.2	41.3	25.31	6
1408 lowa	251.45	504	87.3	43.5	105.32	14
1419 lowa	62.10	190.5	29	14.15	35.78	1
1421 lowa	91.71	252	15.2	13.9	45.67	6
2201 lowa	87.73	540	15.85	14.8	22.47	4
2207 lowa	57.75	360		35.35	25.31	1
2209 lowa	55.74	420		7.95	36.15	3
2221 lowa	63.55	360			20.42	1
2229 Iowa	57.04	240	14.6		11.55	3
2231 lowa	44.56	300	14.5	15.05	12.90	2
2261 lowa	36.74	240		14.25	11.74	1
1603 Kennedy	88.24	240		14.65	51.02	7
1604 Kennedy	139.20	603	28.1	14.2	29.82	13
2019 Lee	95.58	189	73.7		26.09	7
2021 Lee	108.92	254	14.65	15.9	23.68	7
2025 Lee	66.08	254	44.74	16.4	14.46	3
2027 Lee	67.22	222	13.95	26	12.88	5
2029 Lee	26.67	222			25.38	
2031 Lee	54.97	254		28.05	47.39	5
2037 Lee	36.04	286		14.35	47.58	5
2041 Lee	59.42	180		14.9	23.85	4
2045 Lee	33.19	300	14	13.05	10.24	3
2047 Lee	65.25	381		14.25	40.69	6
2109 Lee	116.68	560	14.7	14.55	23.52	4
2115 Lee	61.12	480	14.85	14.9	23.38	2
2119 Lee	87.07	570	17.1		32.85	3
2123 Lee	138.58	317.5	72.7	14.66	26.46	4
2127 Lee	79.80	360	26.85		33.08	5
2135 Lee	52.05	420		14.35	9.90	
2139 Lee	67.62	300	14.85		21.24	5
2143 Lee	40.84	240			10.78	2
2149 Lee	41.07	240			12.00	2
2160/62 Lee	43.04	330			11.48	4
<u></u>						

<u></u>				,	·	
2172 Lee	105.38	150	40.4	13.5	12.18	7
819 Madison	93.08	240	60.6	14.4	21.59	5
907 Madison	78.62	240	69.74	14.8	20.79	5
915 Madison	43.23	180		12.45	42.08	
1009 Madison	26.04	180	13.8	13.65	21.73	
1013 Madison	99.32	270	14.95	27.3	42.58	4
1017 Madison	140.03	240	91.05	89.55	24.35	2
1021 Madison	135.85	254	43.52	15.64	51.42	5
1023 Madison	24.24	95	17.65		26.00	1
1025 Madison	21.49	63.5				2
1027 Madison	18.75	95	32.25		13.85	
1103 Madison	34.82	127	15.9			2
1109/11 Madison	46.52	360		14.8	21.39	3
1122 Madison	61.32	420	66.8	14.9		4
1126/28 Madison	183.12	240	88.6	13.9	41.77	8
1224 Madison	306.46	60	507.75	58.85	12.31	2
1234 Madison	261.01	300	79.6	16.8		8
1244 Madison	250.16	60	317.1	29.9		
1318 Madison	35.58	120				8
1320 Madison	205.52		259.45	90.55		7
1404/06 Madison	78.85		120.3	60.65		
1407 Madison	130.51	360	57.65	14.3	25.35	8
1412/14 Madison	216.50	189	239.02	26.22	20.17	5
1420 Madison	68.07	480	46.6		36.92	5
1424 Madison	153.53	252	63.1	14.05	35.32	7
1426/28 Madison	86.68	220.5	28.5	70.84	54.49	3
2031 Madison	38.49	120	12.52	13.59		4
1611 Maple	63.36	381		12.14	35.05	3
1626 Maple	180.50	540	28		53.44	15
1640 Maple	67.98	189	28.7	13.8	10.99	2
1644 Maple	186.42	409.5	87.6	14.55	63.52	8
1648 Maple	158.61	189	325.5	15	11.54	5
1649 Maple	90.70	285.5	29.65		28.56	5
1708 Maple	49.44	63	14.5	13.8	35.66	2
1713/15 Maple	191.59	840	13.95		82.91	14
1716 Maple	52.92	472.5			44.55	
1726 Maple	117.09	317.5	15	29.6	41.60	7
1727 Maple	53.21	360	13.55		11.90	4
<u> </u>			. 			L

1732 Maple	83.66	254	15.55		35.25	6
1733 Maple	141.47	420			32.55	15
1739 Maple	46.01	420	12.75		45.37	1
1744 Maple	52.46	286		29.35	51.28	
1748 Maple	57.09	508			76.68	
1821 Maple	44.52	381		14.85	53.84	
1933 Maple	42.85	190.5		15.2	36.18	
607 Meredocia	199.41	693	28.85	15.2	71.98	16
615 Meredocia	87.14	480	27.94	14.7		4
616 Meredocia	140.64	540	36.88	7.5		18
627 Meredocia	91.48	600	32.45			11
645 Meredocia	72.12	480	30.15			11
809 Niedringhaus	149.87	660	26.6	29.05	79.89	10
821/23 Niedringhaus	81.57	508	27.55	13.9	39.92	
824 Niedringhaus	62.04	240			12.27	6
915/17 Niedringhaus	245.41	700	118.2		63.30	16
1245/57 Niedringhaus	222.07	1620	102.5	28.05	180.46	3
1500 Niedringhaus	229.71	1920				43
2014 Ohio	394.43	1080	28.2		156.02	32
2018 Ohio	84.12	378	44.2	14.8	38.62	3
2025 Ohio	386.50	4740	40.7		412.37	26
2026 Ohio	77.82	315	15.45	29	35.75	6
1625 Olive	128.56	126	166.22	62.57	23.32	3
1627 Olive	162.43	507	33.15	13.6	111.28	9
1628 Olive	96.36			14.35	105.08	18
1629 Olive	79.95	441	29.05	30.7	70.55	
1631 Olive	155.97	600			38.36	16
1633 Olive	47.78	344			60.63	
1637 Olive	135.60	375	96.45	50.5	56.92	7
1642/44 Olive	25.11	159	15.45	15.15	46.43	
1643 Olive	122.31	315	100.86		67.74	10
1646/48 Olive	33.02	150		28.45	11.62	1
1651 Olive	59.09		75.2			
1717 Olive	67.74	720	44.65	13.7		15
1719 Olive	16.83	127			10.91	
1720 Olive	71.43	378		12.83	11.11	8
1724 Olive	117.27	252	15.37	13.6	45.68	10
1725 Olive	138.80	698.5	18.7	15.35	46.65	12

		, 				
1728 Olive	109.22	381	14.95	13.6	28.37	10
1738 Olive	55.26	94	30.6			3
1740 Olive	55.66	188	14.9	41.91	10.77	3
1744 Olive	73.14	189			46.15	5
1748 Olive	56.28	190.5	15.05	15.55	11.69	2
1750 Olive	82.18	159	18.7	15.35	46.65	12
1021 Reynolds	317.66	990		13.85	216.56	18
1130 Reynolds	49.99	120	14.7		11.94	7
2009/13 Rock	219.76	180	177.92		12.02	8
615 Salveter	137.55	444.5	14.6	30.4	135.72	11
619 Salveter	124.82	819		15.15	19.75	8
1638 Spruce	113.32	480	14.85			12
1642 Spruce	123.64	360	120.02		54.62	6
1720 Spruce	160.70	381	81.65	14.35	22.54	9
1728 Spruce	114.11	420	30.45	14.2	12.53	8
1734 Spruce	70.40	420	29.95	14.4	10.53	5
1740 Spruce	50.73	420			10.57	2
816/916 State	336.42	1920	42.3	16.3	88.20	40
1102 State	180.39	360	82.37		21.86	12
1106 State	172.12	420	92.1	32.15	92.99	10
1118 State	33.44	240		15.1	12.46	3
1120 State	25.35	120			13.31	3
1310 State	146.70	360	44.15	14.85	40.65	6
1322 State	71.65	189	29.15	30.3	34.24	3
1324 State	211.52		268.65	30.3		4
1700 State	266.93		174.9	30.3		12
1704/06 State	185.40		221.05			10
1710 State	102.05	31.5	133.2		3.08	
1712 State	65.87		97.15	69.5		
1716 State	64.23		85.55	27.8		
1930 State	111.55		164			
2117 State	109.94	420	57.4	27.45	17.34	7
2118 State	164.45	1200	21.85			19
2119 State	79.57	420				6
2121 State	94.92	240	27.7	13.9		11
2123 State	76.36	300			9.34	5
2132 State	61.73	360	42.7		6.15	1
2134 State	31.25	180	15.23		<u> </u>	7
2119 State 2121 State 2123 State 2132 State	79.57 94.92 76.36 61.73	420 240 300 360	27.7	13.9	- 	6 11 5 1

2400 01-40	400.05	C 40		45.4	TT	40
2138 State	103.95	540	44	15.1		10
2146 State	191.02	420	14.15	15.05		10
2147/49 State	52.38	180	26.4	14.15		3
2153 State	34.78	240	14.2			3
2155 State	80.93	180	13.05	15.25		2
2158 State	58.98	360	14.65			7
2162 State	50.47	480	28.25	12.4		13
2200 State	116.52	300				9
2204/06 State	56.35	120		13.1		6
2228 State	12.99	180			23.65	
2230 State	19.92	240	<u> </u>	<u> </u>	56.68	
2239 State	68.02	450	29.1	15		6
2247 State	78.04	504	14.95			12
2251 State	67.05	189	28.75	12.6		5
807 Washington	29.96	240	15.5			1
809 Washington	26.58	180	15.1	13.9		3
811 Washington	35.91	180			12.48	2
919/21 Washington	88.46	540			38.87	7
1300/02 Washington	172.48	800			95.38	10
1307/09 Washington	229.05	540	31.65	15.55	349.75	
1317 Washington	76.92	190.5	49.05	15.1	25.09	4
1319 Washington	72.55	159	31.85		34.79	6
1321 Washington	17.48	126				2
1323 Washington	61.18	180	13.15		26.49	5
1325 Washington	38.30	240	12.15		18.10	2
1400/02 Washington	123.90	283.5	13.95	27.7	62.38	6
1405 Washington	201.25	1079.5		40.2	197.93	17
1411 Washington	142.83	378	35.6	29.75	41.95	10
2008 Washington	43.70	180		29.75	9.83	2
2020 Washington	95.74	254	43.75	15.35	13.40	4
2022 Washington	102.93	252	30.36	29.75	22.63	6
2026 Washington	58.40	222	43.35	14.05	13.69	2
2030 Washington	59.75	240	15.4	15.25	13.92	3
2034 Washington	55.20	240	14.25		15.32	4
2036 Washington	25.40	60			4.38	3
2038 Washington	56.87	300	14.26		25.08	4
2104 Washington	47.74	150	31.9	15.65	10.98	<u>·</u>
2108 Washington	117.78	330	74.26	10.00	45.04	4
2.55 7740711191011			,0		10.01	·

Total:	45278.42	175405.00	15194.36	6127.98	14865.06	2805.00
1510 23rd	32.69	60	29.5	16.85		2
1423 22nd	43.11	120	15	13.45		2
1104 21st	26.95	60	32.85	15		
2610 W.20th	38.10	180	41.5	14.15		2
2508 W.20th	136.00	254	57.95	59.35	94.80	6
2506 W.20th	126.86	570	43.32		12.15	9
2504 1/2 W.20th	61.39	190.5	31.85		13.45	3
2504 W.20th	43.45	120	35.15		21.45	
2502 W.20th	234.97	889	29.05		165.61	17
1920 12th	46.78	360	13.95	12.55		4
1518/20 12th	82.38	300		14.6		8
2114 Washington	56.98	320		14.05	24.22	2

6.0 VERIFICATION ANALYTICAL SUMMARY TABLE

6.1 Stack Emission Sites

Stack emission sites were not sampled for verification. This was due to the fact that a predetermined depth for excavation was given to OHM by USACE for each stack emission site.

Stack emission sites are sampled for pre-characterization analysis. Depth's from Woodward/Clyde Sampling are being reviewed by the USEPA and may result in re-sampling.

7.0 PHOTO REPRESENTATION

Photographs and videocassettes documented all sites in all phases of the Granite City project. Each property was documented with before, during, and after photographs and videos. The following sections are representative of the various types of work performed during Phases 1, 2, and 3. Not all properties - only selected representative samples - are presented in this final report, in order to minimize the volume of paper.

2222 Cleveland (Page 7-2)

Top picture – Lot before excavation Middle picture – Lot during excavation Bottom picture – Lot after restoration/sod


1703 Elizabeth (Page 7-3)


Top picture – Lot before excavation Middle picture – Lot during excavation Bottom picture – Lot after restoration/sod

1231 Iowa (Page 7-4)

Top picture – Lot before excavation Middle picture – Lot during excavation Bottom picture – Lot after restoration/sod















APPENDIX A


FLOW CHARTS

APPENDIX A-1	OPERATIONS FLOW CHART
APPENDIX A-2	TECHNICAL EFFORT FOR TRANSPORTATION AND
	DISPOSAL
APPENDIX A-3	TECHNICAL EFFORT FOR SAMPLING
APPENDIX A-4	SITE COORDINATOR FLOW CHART


OPERATIONS FLOW CHART




TECHNICAL EFFORT FOR TRANSPORTATION AND DISPOSAL



TECHNICAL EFFORT FOR SAMPLING



SITE COORDINATOR FLOW CHART



APPENDIX B - REMEDIAL LOCATION WORK DESCRIPTIONS

1920 Adams	2024 Benton	1723 Chestnut
1924 Adams	2028 Benton	1753 Chestnut
1928 Adams	2040 Benton	1753 Chestnut
2034 Adams	2109 Benton	1929 Cleveland
2100 Adams	2113/15 Benton	1935 Cleveland
2108/10 Adams	2117 Benton	1939 Cleveland
2114 Adams	2119 Benton	2006 Cleveland
2116 Adams	2120/22 Benton	2026 Cleveland
2120/22 Adams	2121 Benton	2028 Cleveland
2132/34 Adams	2123 Benton	2029 Cleveland
2144/46 Adams	2124/26/28 Benton	2055 Cleveland
2148 Adams	2129/31 Benton	2057 Cleveland
2156 Adams	2133/35 Benton	2056/58 Cleveland
2158 Adams	2137/39 Benton	2100 Cleveland
2160 Adams	2138 Benton	2110 Cleveland
1022 Alton	2140/42 Benton	
1026 Alton	2153/55 Benton	
1911 Benton	2158 Benton	
1915/17 Benton	2165 Benton	
1916 Benton	2222 Benton	
1919/21 Benton	2226 Benton	
1920 Benton	2228 Benton	
1922 Benton	2231 Benton	
1923 Benton	2240 Benton	
1924 Benton	2248 Benton	
1925/27 Benton	2250 Benton	
1926 Benton	2252 Benton	
1928 Benton	2254 Benton	
1930 Benton	2256 Benton	
1932 Benton	2013/15 Bryan	
1934 Benton	2023 Bryan	
1936 Benton	2027 Bryan	
1937 Benton	2029/31 Bryan	
1940 Benton	2037 Bryan	
1941 Benton	2103 Bryan	
1943 Benton	1715 Chestnut	
2020 Benton	1718/20 Chestnut	

1920 Adams

Action Date: 6/24/97

Loadout: 6/25/97

Restoration Begins: 6/26/97 Restoration Completed: 7/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 113.96 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Keeven sod farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1920 ADAMS

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	
155.18	268.27	46.2	28.84	960	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	0 - 0	I TOTIL AIR DA		
	Α	Α	Α	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	

3 - 6" Front and Back

-	, , , , , , ,	
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1920 Adams

590

580


418

63

193

40

3



1924 Adams

Action Date: 12/8/97

Loadout: 12/8/97

Restoration Begins: 12/11/97 Restoration Completed: 12/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 101.13 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

1924 ADAMS

:	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE	OTHER
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.		
_	115.86	6	19.18	44.75	14.6	420		

1

Sampling malysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1924 Adams **635 1223**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

460 582


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


286 **549** 97 324 85 **848**

Depth Excav. (inch)

12



X = SAMPLE POINT



~			
\smile			
•			

1928 Adams

Action Date: 7/17/97

Loadout: 7/17/97

Restoration Begins: 7/21/97 Restoration Completed: 8/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 89.12 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

1928 ADAMS

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE	OTHER
 (TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	<u> </u>	
115.86	6	19.18	44.75	14.6	420		

Sampling malysis
Project #19531

0 - 3"	Front	and	Back
_	1 _		_

	0 - 0	I TOTIL at	IU Dack
	Α	Α	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1928 Adams	530	353
	361	600

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

558	280
259	577


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

915	25
145	223
324	349

Depth	_
Excav.	
(inch)	

6



X = SAMPLE POINT

1928 ADAMS
47' X 108'

OHM Corporation
Corporation
Findlay Ohio

Drawn By:
7/29/98
Scale: NTS Drawing No:

-

2034 Adams

Action Date: 4/21/98 ____oadout: 4/24/98

> Restoration Begins: 4/24/98 Restoration Completed: 5/14/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 301.14 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm


QUANTITY SUMMARY FOR

2034 Adams

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)_	(TONS)	(TONS)	CU.YDS.		
391.84	35	60				1260		

Sampling Analysis Project #19531

	0 - 3" Front and Back			3-6" Front and Back			6-12" Front and Back			
Street/Number	A PPM	A PPM	A PPM	B PPM	B PPM	B PPM	C	C	C	Depth
Address	No.	No.	No.	No.	No.	No.	PPM No.	PPM No.	PPM No.	Excav. (inch)
2034 Adams	264 160	227 750		223 133	217 8398		183 87	119 7043		12
	193	774		191	668		158	536		



`` ``

2100 Adams

Action Date: 10/16/97

Loadout: 10/20/97

Restoration Begins: 10/20/97 Restoration Completed: 11/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 319.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2100 ADAMS

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
_	415.03	15	103.98	54.8	26.7		840		

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В		
PPM	PPM	PPM		
No.	No.	No.		

6 - 12" Front and Back

С	С	С		
PPM	PPM	PPM		
No.	No.	No.		

Depth Excav. (inch)

2100 Adams


586

872

436 882

23651965


12



BI 15' from bour 12' from Sidewalk

32 10' from Sind 12' from PP

- /



2108/10 Adams

Action Date: 9/16/97

Loadout: 9/18/97

Restoration Begins: 9/23/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 36.34 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2108/10 ADAMS

i	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	1	·
	47.25		26.7	14.65			240		

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2108/10 Adams 135


538 471

182

245 208

97

99 108





2114 Adams

Action Date: 9/18/97

Loadout: 9/20/97

Restoration Begins: 9/20/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 77.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2114 ADAMS

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>	
101.01	5	53.38	57.95			600		

0 - 3" Front and Back

	0 0	I I OI IL CI	IG DGGI
	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

0 - 0	I TOTIL GI	IG DUCK
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2114 Adams

268


914

198


670

29

634



103-116 19-13-20-401-013 WTBO
-E/2110 . 401-011 C07327
401-010 C0733. NO



2116 Adams

Action Date: 9/24/97 Loadout: 9/26/97

Restoration Begins: 9/26/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 146.81 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2116 Adams

SF	PECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
	190.86	26	135.73	13.79	28.35		360		

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2116 Adams

241

339

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


240 184

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

154 **637**239 **2031**

Depth Excav. (inch)



•			
_			

2120/22 Adams

Action Date: 4/17/97

Loadout: 4/17/97

Restoration Begins: 4/18/97 Restoration Completed: 5/14/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 103.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2120/22 ADAMS

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7 S/	AND SOD	CONCRETE	OTHER
Ŀ	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS) (TO	ONS) CU.YDS.		
	134.3	8	91.04			420		

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2120/22 Adams 639 715 1020

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

465 496 **1080**


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

454 717 436

12

Depth Excav. (inch)



_

~			

2132/34 Adams

Action Date: 4/28/97

Loadout: 4/29/97

Restoration Begins: 4/30/97 Restoration Completed: 5/15/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 86.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2132/34 ADAMS

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
112.65	7	44.82	56.48	14.27		300	

(

0 - 3" Front and Back

	Δ	Δ	Δ
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2132/34 Adams **547 2650**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


434 454 **623 1405**

6 - 12" Front and Back

C	С	С
PPM	PPM	PPM
No.	No.	No.

535 152488 1071

Depth Excav. (inch)



~			
_			
Ų			

2144/46 Adams

Action Date: 10/11/97

Loadout: 10/15/97

Restoration Begins: 10/15/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 137.88 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2144/46 ADAMS

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>	
179.25	10	30.38	40.55	26.95		360		

0 -	3"	Front	and	Back
-----	----	-------	-----	------

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2144/46 Adams 246 **556 3000 1010**


3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

126 **606** 248 221 238 262 6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

99 **506** 110 101 175 **529** Depth Excav. (inch)





2148 Adams

Action Date: 5/15/97

Loadout: 5/16/97

Restoration Begins: 5/19/97 Restoration Completed: 6/2/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 146.62 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2148 ADAMS

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>	
190.61	3	34.66	86.9	28.5		270		

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2148 Adams 529 1460

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


269234240

6 - 12" Front and Back


•		
С	С	С
PPM	PPM	PPM
No.	No.	No.

68 **1290** 313 **5109**

Depth Excav. (inch)











.

2156 Adams

Action Date: 10/22/97 __Loadout: 10/27/97

Restoration Begins: 10/27/97 Restoration Completed: 11/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 106.55 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331 *17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2156 Adams

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
L	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
	138.52	8	17.82	30.05	28.4		240		

.

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2156 Adams

546

461

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.

151 658 602 323

6 - 12" Front and Back					
C	С	С			
PPM	PPM	PPM			
No.	No.	No.			

651 116 404 158

Depth Excav. (inch)



•

2158 Adams

Action Date: 10/22/97 Loadout: 10/23/97

Restoration Begins: 10/27/97 Restoration Completed: 11/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 60.29 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

QUANTITY SUMMARY FOR

2158 ADAMS

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAN	ID SOD	CONCRETE OTHER	
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TON	IS) CU.YDS.	<u> </u>	_
78.38	6	32.91				180	· · · · · · · · · · · · · · · · · · ·	•

0 - 3" Front and Back

Α A Α PPM PPM PPM Street/Number No. No. No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2158 Adams

Address


1040

570

1044

622

371 815 390 429



••			
\sim			
\smile			

2160 Adams

Action Date: 3/30/98 Loadout: 4/2/98

Restoration Begins: 4/2/98 Restoration Completed: 4/18/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 100.40 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Grantham-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

2160 Adams

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
130.52	8		39.6			240		

(

0 - 3	3" Fr	ont a	nd B	ack
-------	-------	-------	------	-----

O O I TOTA ATTA DAGA			
Α	Α	Α	
PPM	PPM	PPM	
No.	No.	No.	
	A PPM	A A PPM PPM	

2160 Adams	290	379
	178	505
	249	735

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


164	324
107	612
116	730

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

48	239
69	504
52	795

Depth
Excav.
(inch)



1022 Alton

Action Date: 10/21/97

Loadout: 10/27/97

Restoration Begins: 10/27/97 Restoration Completed: 10/31/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 152.96 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

1022 Alton

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE OTHER
_	_(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>
_	198.86	10	61.39	72.35	21.98		480	

(

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1022 Alton

510

428

В	В	В
PPM	PPM	PPM
No.	No.	No.


511 385 256 510


3 - 6" Front and Back

6 - 12	6 - 12" Front and Back						
С	C	C					
PPM	PPM	PPM					
No.	No.	No.					

598 224 541 208

Depth Excav. (inch)





. .

1026 Alton

Action Date: 10/21/97

Loadout: 10/28/97

Restoration Begins: 10/28/97 Restoration Completed: 10/31/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 124.53 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

1026 Alton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE	OTHER
 (TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.		
161.89	5	43.36	42.3	21.63	420	<u> </u>	

	0 - 3" Front and Back				
	Α	Α	Α		
Street/Number	PPM	PPM	PPM		
Address	No.	No.	No.		

1026 Alton	462	258
	303	397
	402	423

3 -	6"	Front	and	Back
-----	----	--------------	-----	------

В	В	В
PPM	PPM	PPM
No.	No.	No.


310	474
237	141
353	548

6 -	12"	Front	and	Back

•	• •	
С	С	С
PPM	PPM	PPM
No.	No.	No.

119	97
150	54
239	223

Depth	
Excav.	
(inch)	



\smile		
_		
\smile		

1911 Benton

Action Date: 7/14/97 Loadout: 7/15/97

> Restoration Begins: 7/16/97 Restoration Completed: 8/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 50.78 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

QUANTITY SUMMARY FOR

1911 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	<u> </u>	
66.02	52.58	12.8	14.07	180		

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С	
PPM	PPM	PPM	
No.	No.	No.	


Depth Excav. (inch)

1911 Benton

915 1111201 880

255 176

143 299



X = SAMPLE POINT

1911 BENTON
50' X 122'

OHM Corporation
Findlay Ohio

Drawn By:
T/29/98
Scale: NTS Drawing No:



1915/17 Benton

Action Date: 6/30/97 Loadout: 7/1/97

Restoration Begins: 7/1/97 Restoration Completed: 7/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 64.76 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

QUANTITY SUMMARY FOR

1915/17 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	: i	
84.19	5	40.93	14.65	14.3		210		

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


C	С	С	
PPM	PPM	PPM	
No.	No.	No.	

Depth Excav. (inch)

1915/17 Benton 326 1110

527 1210

128 437



.

1916 Benton

Action Date: 3/12/97

Loadout: 3/20/97

Restoration Begins: 3/20/97 Restoration Completed: 3/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 35.76 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Petago Sod Farm

QUANTITY SUMMARY FOR

1916 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND SOD	CONCRETE OTHER
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS) CU.YDS.	
46.49	1 30	29.65 31	150	!

(

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


Depth Excav. (inch)

1916 Benton

577 128467 248

337 209

182 44



Bi I'NOT WALKWAY

21' WOF house

House & Paricment = 70%

BZ 17' Sol fonce 12' Wot shed

>			

1919/21 Benton

Action Date: 6/5/97

Loadout: 6/6/97

Restoration Begins: 6/7/97 Restoration Completed: 6/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 63.92 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

1919/21 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
83.1	50.98	31.15	44.8		180		

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)


1919/21 Benton **798**

798 1675

367

95

84 250



الى آپ

71 x			
. *			
_			

1920 Benton

Action Date: 3/20/97 —Loadout: 3/22/97

> Restoration Begins: 3/24/97 Restoration Completed: 4/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 25.13 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

QUANTITY SUMMARY FOR

1920 Benton

OTHER		:
CONCRETE		
SOD	CU.YDS.	120
SAND	(TONS)	
CA-7	(TONS)	14.9
CA-6	(TONS)	
L TOPSOIL	(TONS)	28
BACKFILL	(LOADS)	
SPECIAL WASTE	(TONS)	32.68

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

			<u> </u>
	C	С	С
	PPM	PPM	PPM
	No.	No.	No.
Ĺ			

Depth Excav. (inch)

1920 Benton


639

686

300 335

53

117



X = SAMPLE POINT

1920 BENTON

TOTAL

DEMINSIONS

99'X31'


Corporation
Findley, Ohio

Drawn By: Chec

Drawn By: Checked By:

Date: Approved By:

Scale: NTS Drawing No:



1922 Benton

Action Date: 3/22/97

Loadout: 3/24/97

Restoration Begins: 3/24/97 Restoration Completed: 4/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 26.24 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

QUANTITY SUMMARY FOR

1922 Benton

i	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
	34.12		12		14.8	I !	120		

0 - 3" Front and Back

	0 0	1 10116 01	ia back
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1922 Benton 367 **709 513 736**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

319 **521** 410 297


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

216 364

6

Depth Excav. (inch)



House & Paviment = 80%

z. - /

_			
_			
\longrightarrow			
	·		
	·		
	·		

1923 Benton

Action Date: 6/4/97

Loadout: 6/5/97

Restoration Begins: 6/7/97 Restoration Completed: 6/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 60.63 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

QUANTITY SUMMARY FOR

1923 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
78.83			32.55	46.7				

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1923 Benton **516** 257 432 444

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

376 132


6 - 12" Front and Back


С	C	С
PPM	PPM	PPM
No.	No.	No.

223 70

3

Depth Excav. (inch)





Ų			

1924 Benton

Action Date: 4/1/97

Loadout: 4/2/97

Restoration Begins: 4/3/97 Restoration Completed: 4/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.68 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

QUANTITY SUMMARY FOR

1924 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD CONC	RETE OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
60.69	2	16	16.45	16.6	. -	120	

0 - 3" Front and Back

	A	A	A
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1924 Benton

550


651

903

616

624

522



•			
•			
	,		
~			
Nuc.			
•			

1925/27 Benton

Action Date: 6/21/97

Loadout: 6/23/97

Restoration Begins: 6/23/97 Restoration Completed: 7/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 32.00 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1925/27 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND SOD CONCE	RETE OTHER
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS) CU.YDS.	_
41.6	63.74		420	

Sampling malysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1925/27 Benton **626**

26 91

916


335

347

116

327

3



<u></u>			
•			
\smile			

Action Date: 3/31/97

Loadout: 4/2/97

Restoration Begins: 4/2/97 Restoration Completed: 4/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 33.63 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Kobotoa

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1926 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
43.73	14.74	17.5			150		

(

Sampling malysis
Project #19531

0 - 3" Front and Back

0	I TOTIC CI	IG DGOIN
Α	A	Α
PPM	PPM	PPM
No.	No.	No.
	A PPM	

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1926 Benton

660


415

129 242

23

212

3



House & Parement = 90%

12 OK

·		
<u>~</u>		
<u> </u>		
_		
~		

Action Date: 7/22/97

Loadout: 7/24/97

Restoration Begins: 7/24/97 Restoration Completed: 8/20/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 51.27 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*Roller

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

1928 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	!	
66.66	1	36.04	26.3	14.6		240		

Sampling malysis
Project #19531

0 - 3" Front and Back

	O O I TOTIL GITG DOOK				
	Α	Α	Α		
Street/Number	PPM	PPM	PPM		
Address	No.	No.	No.		

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

63

Depth Excav. (inch)

1928 Benton

835


404

167

141

45

3





Action Date: 3/26/97

Loadout: 3/27/97

Restoration Begins: 3/28/97 Restoration Completed: 4/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 50.84 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedago Sod Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1930 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
66.1	2	77.22	42.09			240		

í

Sampling Analysis
Project #19531

0 - 3" Front and Back

	A A A		
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1930 Benton

570

420

459

574

183

136

6

e e			
X 2			
y			
<u>~</u>			

Action Date: 7/26/97

Loadout: 7/29/97

Restoration Begins: 10/8/97 Restoration Completed: 10/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 37.81 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

1932 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
49.16		45.43		15.45		240		

(

Sampling hualysis Project #19531

	0 - 3" Front and Back			
	Α	Α	Α	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	

1932 Benton	188 49	312 91
	846	222
	107	216

\sim		Front		D = =1.
	- n	Front	าลทฤ	васк

В	В	В
PPM	PPM	PPM
No.	No.	No.

256	246
678	163
491	185


6 -	12"	Front	and	Rack
n -	1/	FIOH	anc	DACK


С	С	С
PPM	PPM	PPM
No.	No.	No.

82	361
49	51
50	107

Depth
Excav.
(inch)

3





•

Action Date: 4/8/97

Loadout: 4/9/97

Restoration Begins: 4/14/97 Restoration Completed: 4/25/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 30.82 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1934 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	_(TONS)	(TONS)	CU.YDS.	1	
40.07	44.3		·		180		

Sampling Analysis Project #19531

1934 Benton

0 - 3" Front and Back

520

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

185

3 - 6" Front and Back							
В В В							
PPM	PPM	PPM					
No.	No.	No.					

404

877


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

257 318

6

Depth Excav. (inch)



BI I' E of wall il! S of force

BZ 7' wot shop 20'S of funce 60% Paved

·			

Action Date: 8/12/97

Loadout: 8/13/97

Restoration Begins: 8/14/97 Restoration Completed: 8/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 58.43 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26 *17-KW *TCM

*Roller

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

1936 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		1
75.96	3	15.61	29.05	16.7		300		

ĺ

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1936 Benton 474 470

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

557 310 **1055** 460


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


190 170

6

Depth Excav. (inch)









Action Date: 6/18/97

Loadout: 6/19/97

Restoration Begins: 6/19/97 Restoration Completed: 7/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 77.24 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1937 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)_	(TONS)	(TONS)	(TONS)	CU.YDS.		
100.42	4	23.85	27.65	29.6		360		

(

0 - 3" F	ront	and	Back
----------	------	-----	------

	0 0	i i Oi it ai	IG DUCK
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1937 Benton	168	668
	95	447

3	- 6"	Froi	nt a	nd	Back
J	- 0	1 10	ווכ	ıı.	Dack


	1 10116 01	14 5401
В	В	В
PPM	PPM	PPM
No.	No.	No.

184	573
154	509

6 -	12"	Front	and	Rack

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth	
Excav.	
(inch)	





Action Date: 4/18/97

Loadout: 4/25/97

Restoration Begins: 4/26/97 Restoration Completed: 5/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 34.23 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1940 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	. CA-6	CA-7	SAND	SOD	CONCRETE OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
44.51	77.19				360	

í

1940 Benton

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

479 **987**

3 - 6" Front and Back

0	i ioni ai	ia Daois
В	В	В
PPM	PPM	PPM
No.	No.	No.

470

114


6 - 12	" Front a	and Back
C	С	C
PPM	PPM	PPM
No.	No.	No.

48 252

3

Depth Excav.

(inch)



X = SAMPLE POINT

1940 BENTON
47' X 98'

OHM Corporation
Findlay, Ohio

Drawn By:
T/28/98
Scale: NTS Drawing No:



Action Date: 6/11/97

Loadout: 6/12/97

Restoration Begins: 6/12/97 Restoration Completed: 6/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 23.17 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1941 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND SOD	CONCRETE OTHER
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS) CU.YDS.	
30.13	61.73	28.9	120	

ĺ

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

	1 70112 01	IG DGOIL
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1941 Benton


611 1240

441

384

81

245



B1 3' to Sidewalk

House & Paved ana = 70%

BZ 20' to house 25' tostence

- wok 1 ..

Action Date: 6/10/97

Loadout: 6/11/97

Restoration Begins: 6/12/97 Restoration Completed: 6/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 20.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1943 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	1	
30.13		61.73		28.9		120		

(

0 - 3" Front and Back

		i i Oi it ai	a Daoit
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

317

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

1943 Benton


520

447

244

43

115



 $\overline{}$

:			

Action Date: 9/2/97

Loadout: 9/3/97

Restoration Begins: 9/5/97 Restoration Completed: 9/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 60.91 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2020 Benton

SPECIAL WASTE	BACKFILL TOPSOIL CA-	6 CA-7 SAND SOD CONCRETE OTHER	₹
(TONS)	(LOADS) (TONS) (TON	S) (TONS) (TONS) CU.YDS.	
79.19	74.31	510	

0 - 3" Front and Back

O O I TOTAL GITA D			u Duoit
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2020 Benton 476 **693**

3 - 6" Front and Back


0 0	I TOTAL CAL	ia Daoii
В	В	В
PPM	PPM	PPM
No.	No.	No.

190 404

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

696 85 143 69 120 261 Depth Excav. (inch)



B1 6' From Front Wall

1 8' From Walk into horse

B2 9' to N fence

25' to Shed

Horse : Parement = 60%

48 St An

$\widetilde{}$			
\smile			
\smile			
\smile			

Action Date: 9/5/97
Loadout: 9/8/97

Restoration Begins: 9/8/97 Restoration Completed: 9/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.88 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

2024 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS) (TONS) ((TONS)_ CU.YDS.		
62.25	49.5		28.3	300		

0 - 3" Front and Back

0-3	rioni ai	iu back
Α	Α	Α
PPM	PPM	PPM
No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2024 Benton


Street/Number

Address

558 377461 286

265 409

116 363



B'- 81 north of house if 4' east of doiner of house.

16' west of shed & 34' south of house



2028 Benton

Action Date: 4/30/97

Loadout: 5/5/97

Restoration Begins: 5/5/97 Restoration Completed: 5/16/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 80.46 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2028 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	
104.61	1	59.53	44.7	14.7		210	1

Sampling Analysis
Project #19531

	0-3	Front ar	iu back
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2028 Benton	986	423
	440	260

3 - 6" Front and Back				
В	В	В		
PPM	PPM	PPM		
No.	No.	No.		


271	504	186
439	400	

6 - 12" Front and Back				
С	С	С		
PPM	PPM	PPM		
No.	No.	No.		

95	213	6

Depth Excav.

(inch)



· <u> </u>			
~			

2040 Benton

Action Date: 8/27/97 __Loadout: 8/28/97

> Restoration Begins: 8/29/97 Restoration Completed: 9/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.39 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2040 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
61.61	2	15.62	43.55			240		

Sampling malysis
Project #19531

0 - 3" Front and Back

	O O HOIR and Back		
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2040 Benton

707


416

752

479

474

383



Both of horse & let east of fence.

-			
\smile			

2109 Benton

Action Date: 9/30/97

Loadout: 10/2/97

Restoration Begins: 10/2/97 Restoration Completed: 10/16/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 117.20 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2109 Benton

SPECIAL WASTE	BACKFILL TOPSO	IL CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) : (TONS) (TONS)	(TONS)	(TONS)	CU.YDS.	· -	
152.36	8 52.21	29.7	13.6		360		

,

Sampling nalysis Project #19531

0 - 3" Front and Back 3 - 6" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2109 Benton

431

690

В	В	В
PPM	PPM	PPM
No.	No.	No.


282	555
174	160
352	586

С	С	С
PPM	PPM	PPM
No.	No.	No.

690	254
63	57
418	410

6 -	· 12"	Front	and Back

Depth	
Excav.	
(inch)	_





2113/15 Benton

Action Date: 4/14/97

Loadout: 4/15/97

Restoration Begins: 4/15/97 Restoration Completed: 5/8/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 118.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2113/15 Benton

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER	
_	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.			
	153.8	8	74.37				420			1

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2113/15 Benton 472 1380

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


427 3100

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

291 **546** 170 **842**

Depth Excav. (inch)



B2- 14' west of fence z' 22' north of hise.

\smile		
		
	•	
\sim		

2117 Benton

Action Date: 5/27/97 Loadout: 5/28/97

> Restoration Begins: 5/28/97 Restoration Completed: 6/13/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 30.5 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2117 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
39.65	2	14.02	13.45	14.1		120		

Sampling malysis
Project #19531

0 - 3" Front and Back

	0 - 0 TOTAL ATTA DACK					
	Α	Α	Α			
Street/Number	PPM	PPM	PPM			
Address	No.	No.	No.			

2117 Benton 237 **634** 212 438

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

270 **571**219 **971**

6 - 12" Front and Back


CCC	
PPM PPM PPM	
No. No. No.	

57 191

(inch)

6

Depth Excav.



•			
)			
\ /			

2119 Benton

Action Date: 10/4/97

Loadout: 10/8/97

Restoration Begins: 10/8/97 Restoration Completed: 10/16/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 94.02 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

2119 Benton

SPECIAL WASTE	BACKFILL	TOPSOĪL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u> </u>	
122.23	1	15.51				240	· · · · · · · · · · · · · · · · · · ·	

!

Sampling malysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2119 Benton 323 303 188

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

316 218 **542** 230 **592**


6 - 12" Front and Back

621

С	С	С
PPM	PPM	PPM
No.	No.	No.

116 32137 **620**

Depth Excav. (inch)



B1 7' Sof funce 8' Wof funce Bi 4' Not Long Zo' E of Long



2120/22 Benton

Action Date: 7/10/97

Loadout: 7/11/97

Restoration Begins: 7/12/97 Restoration Completed: 7/23/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 72.66 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

2120/22 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	_(TONS)	(TONS)	CU.YDS.		
94.46	4	74.34				420		

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2120/22 Benton 489 **583**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

337 **604** 272 **4643**


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

190 58

6

Depth Excav. (inch)



<u> </u>			
→			

2121 Benton

Action Date: 10/4/97

Loadout: 10/9/97

Restoration Begins: 10/9/97 Restoration Completed: 10/21/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.75 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2121 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6 CA-7	SAND SOD	CONCRETE OTHER
(TONS)	(LOADS) (TONS)	(TONS) (TONS)	(TONS) CU.YDS.	
62.08	16		180	

Sampling Analysis Project #19531

0 - 3" Front and Back

	O O HORK GIRG DOOK				
	Α	Α	Α		
Street/Number	PPM	PPM	PPM		
Address	No.	No.	No.		

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)


2121 Benton

338 **745 699 774**

4

415 455

148 325



<u></u>			
·			
X			
		•	
~			

2123 Benton

Action Date: 12/15/97

Loadout: 12/16/97

Restoration Begins: 12/16/97 Restoration Completed: 12/18/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 29.89 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2123 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
38.86	3		15.3		180		

(

Sampling Analysis
Project #19531

0 - 3" Front and Back

A A A
Street/Number PPM PPM PPM
Address No. No. No.

3 - 6" Front and Back

B B B
PPM PPM PPM
No. No. No.

6 - 12" Front and Back

C C C
PPM PPM PPM
No. No. No.

360

Depth Excav. (inch)

2123 Benton


345

541


510

464

109



et "



2124/26/28 Benton

Action Date: 5/4/97

Loadout: 5/16/97

Restoration Begins: 5/17/97 Restoration Completed: 6/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 123.86 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2124/26/28 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	
161.02	6	68.34	76.59		660	

Sampling Analysis
Project #19531

•	0 - 3" Front and Back					
	Α	Α	Α			
Street/Number	PPM	PPM	PPM			
Address	No.	No.	No.			

3 - 6"	Front ar	nd Back
В	В	В
PPM	PPM	PPM
No.	No.	No.


C	Front	C
PPM	PPM	PPM
No.	No.	No.

Depth	
Excav.	
(inch)	

2124-28 Benton 399

178 415

383 246 **590** 208 **630** 141 46 377



B2-All gravel in backgard. eff br

· ~			
→			
_			

2129/31 Benton

Action Date: 5/1/97

Loadout: 5/5/97

Restoration Begins: 5/8/97 Restoration Completed: 5/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 32.16 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.


QUANTITY SUMMARY FOR

2129/31 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
41.81				17.55		150		

√ Sampling Analysis Project #19531

U - 3	Front a	nd Back	3-6"	Front an	d Back	6-12"	' Front a	nd Back	
A PPM	A PPM	A PPM	B PPM	B PPM	B PPM	C PPM	C PPM	C PPM	Depth Excav. (inch)
•		, NO.		-	NO.			NO.	Zincii)
	Α	A A PPM PPM No. No.	A A A PPM PPM PPM No. No. No.	A A A B PPM PPM PPM No. No. No. No.	A A A B B PPM PPM PPM PPM No. No. No. No. No.	A A A B B B PPM PPM PPM PPM No. No. No. No. No. No.	A A A B B B C PPM PPM PPM PPM PPM No. No. No. No. No. No. No.	A A A B B B C C PPM PPM PPM PPM PPM PPM PPM No. No. No. No. No. No. No. No.	A A A B B B C C C PPM PPM PPM PPM PPM PPM PPM No. No. No. No. No. No. No. No.



._

2133/35 Benton

Action Date: 5/1/97

Loadout: 5/5/97

Restoration Begins: 5/5/97 Restoration Completed: 5/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 39.55 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2133/35 Benton

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
51.42		74.45	16.25		150		

Sampling Analysis
Project #19531

0 - 3" Front and	l Back
------------------	--------

	0 0 Hork and Back					
	Α	Α	Α			
Street/Number	PPM	PPM	PPM			
Address	No.	No.	No.			

2133/35 Benton	560	341
	309	655

3 -	6"	F	ron	t ar	hr	Ra	ck


0 0	I TOTAL GI	ia Daoi
В	В	В
PPM	PPM	PPM
No.	No.	No.


604	243
276	389
352	699


6 - 12" Front and Back	6	- 12"	Front	and	Back
------------------------	---	-------	-------	-----	------

С	С	С
PPM	PPM	PPM
No.	No.	No.

	С	C	Depth
1	PPM	PPM	Excav.
	No.	No.	(inch)







2137/39 Benton

Action Date: 5/1/97

Loadout: 5/6/97

Restoration Begins: 5/6/97 Restoration Completed: 5/20/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 127.22 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2137/39 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	ĊA-7	SAND	SOD	CONCRETE OTHER	
(TONS)_	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		_
165.39	10	90.21	28.35			180		-

Sampling Analysis Project #19531

0 - 3" Fi	ront and	Back
-----------	----------	------

	O - O TION WING DOOK			
	A	Α	Α	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	

3 -	6''	Fro	nt ar	nd	Back
-----	-----	-----	-------	----	------

В	В	В
PPM	PPM	PPM
No.	No.	No.


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.


Depth
Excav.
(inch)

2137/39 Benton 326 621 128 330 319 318

511 207 497 274



X = SAMPLE POINT



~		
THE STATE OF THE S		
\smile		

2138 Benton

Action Date: 5/19/97

Loadout: 5/20/97

Restoration Begins: 5/21/97 Restoration Completed: 6/7/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 126.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2138 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)_	(TONS)	CU.YDS.		
164.72	3	151.47	29.3	14.5		444		

Sampling Analysis
Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2138 Benton **570** 460

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

530 260345 232696 432

6 - 12" Front and Back


· · · · ·		
С	С	С
PPM	PPM	PPM
No.	No.	No.

110 100

_

6

Depth Excav. (inch)



X = SAMPLE POINT

2138 BENTON

TOTAL

DIMENSIONS

130' X 97'

Date: Approved By:

Scale: Drawing No:



2140/42 Benton

Action Date: 7/7/97

Loadout: 7/8/97

Restoration Begins: 7/9/97 Restoration Completed: 7/18/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 57.17 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

2140/42 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SO	D CONCRETE	OTHER
(TONS)	(LOADS)	_(TONS)	(TONS)	(TONS)	(TONS) CU.Y	DS.	<u>:</u>
74.33	2	63.27	14.35	13.95	31	7	

1

Sampling malysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

PPM	PPM	PPM
No.	No.	No.

3 - 6" Front and Back

В

В

" Front a	and Back
С	С
PPM	PPM
No.	No.
	C PPM

Depth Excav. (inch)

2140/42 Benton 402

523


417 618

В

230

157


6



B1 4' from front walk
2' from Walk into house
B232' from house
2' from walk

House Ephrement = 50%

10/



2153/55 Benton

Action Date: 5/12/97

Loadout: 5/13/97

Restoration Begins: 5/14/97 Restoration Completed: 5/20/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 96.49 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2153/55 Benton

SPECIAL WASTE	BACKFILL TO	OPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
125.44		31.88		13.5		378		

•

Sampling Analysis
Project #19531

	U - 3" Front and Bac		
	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2153/55 Benton 248 **963** 218 **514**

3 - 6"	3 - 6" Front and Back				
В	В	В			
PPM	PPM	PPM			
No.	No.	No.			

142 **814 545**


0 - 12	" Front a	and Ba
С	C	C
PPM	PPM	PPM
No.	No.	No.


55

186 96

Depth Excav. (inch)

6





2158 Benton

Action Date: 5/28/97

Loadout: 5/29/97

Restoration Begins: 5/29/97 Restoration Completed: 6/5/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 64.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.


QUANTITY SUMMARY FOR

2158 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7 SAND SOD CONCRETE OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS) (TONS) CU.YDS.
84.05	3	74.87	14.8	444.5

Sampling Analysis Project #19531

	0 - 3"	0 - 3" Front and Back			Front an	d Back	6-12'	6-12" Front and Back		
Street/Number Address	A PPM No.	A PPM No.	A PPM No.	B PPM No.	B PPM No.	B PPM No.	C PPM No.	C PPM No.	C PPM No.	Depth Excav. (inch)
2158 Benton	353 9536	555 373	380	183 406	524 604	331	61	257	162	6



2165 Benton

Action Date: 5/29/97

Loadout: 6/2/97

Restoration Begins: 6/2/97 Restoration Completed: 6/3/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 42.24 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2165 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	_(TONS)	CU.YDS.		
54.92		30.36				190.5	i -	

′

Sampling Analysis
Project #19531

0 - 3" Front and Back

	-	1 I OI IL CI	IG DGOIL
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

0 0	i i Oi it ai	ia baon
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	C
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2165 Benton

846


306

44 749


572

575

12



X = SAMPLE POINT





2222 Benton

Action Date: 9/8/97

Loadout: 9/11/97

Restoration Begins: 9/11/97 Restoration Completed: 9/29/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 229.47 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*****X331

*17-KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Grantham-trucking
 - *Schneider-turf farm

QUANTITY SUMMARY FOR

2222 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
298.32	5	108.05	76.55	25.35		540		

Sampling malysis
Project #19531

0 - 3" Front and Back

	0 0	i i Oi it ui	id Daoit
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

C	С	C
PPM	PPM	PPM
No.	No.	No.

365

Depth Excav. (inch)

2222 Benton

748


198

574

540

226

6



2226 Benton

Action Date: 9/2/97

Loadout: 9/4/97

Restoration Begins: 9/4/97 Restoration Completed: 9/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 82.88 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Sod Farm

QUANTITY SUMMARY FOR

2226 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	1	
107.75	6	42	44.4	14.6		240		

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

В В В PPM PPM PPM No. No. No.

3 - 6" Front and Back

47

C

PPM

No.

337

6 - 12" Front and Back

C

PPM

No.

С

PPM

No.


Depth Excav. (inch)

2226 Benton

527

533

404 660



\checkmark			

Action Date: 9/2/97
Loadout: 9/3/97

Restoration Begins: 9/5/97 Restoration Completed: 9/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.76 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Sod Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	1	
60.8		58.85			<u> </u>	360	· · · ·	

0 - 3" Front and Back

	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	C C			
PPM	PPM	PPM		
No.	No.	No.		

Depth Excav. (inch)

2228 Benton

700


689

226

337

83

154



<u> </u>			
\checkmark			
_			
-			
\sim			

Action Date: 5/11/98 Loadout: 5/14/98

> Restoration Begins: 5/13/98 Restoration Completed: 5/19/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 42.30 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

SPECIA	AL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
Τ)	ONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
	55	4		30.5	27.1		360		

2231 Benton

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

886 192778 1182

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

217 104


6 - 12" Front and Back

_ `		2. IG <u>B</u> GO.		
С	С	С		
PPM	PPM	PPM		
No.	No.	No.		


47 47

3

Depth Excav. (inch)



X = SAMPLE POINT





Action Date: 5/15/98 Loadout: 5/16/98

Restoration Begins: 5/18/98 Restoration Completed: 5/21/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 49.50 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2240 Benton

SPECIAL WAS	STE BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
64.36	5			14.5		300		

(

2240 Benton

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

555 99375 3081167 408

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

87 498


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

24 238

3

Depth Excav. (inch)



X = SAMPLE POINT

2240 BENTON 52' X 130'



Drawn By EDJ	Checked By:
Date: 7/29/98	Approved By:
Scale: NTS	Drawing No:

<u> </u>	
4	
<u>.</u>	
_	

Action Date: 8/4/97
Loadout: 8/7/97

Restoration Begins: 8/7/97 Restoration Completed: 8/26/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 30.78 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*Kubota

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Sod Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	·	
40.02		17.33		30.4		60		

0 - 3" Front and Back

Α A A Street/Number PPM PPM PPM No. No. No.

3 - 6" Front and Back

0 0		IG DGOIL
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2248 Benton

Address


524 518


262

317

222 254 63

34 107





Action Date: 8/6/97 _ Loadout: 8/8/97

> Restoration Begins: 8/14/97 Restoration Completed: 9/4/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 33.16 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*KABOTA

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2250 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
43.12		30.75	14.55	14.65		420		

ĺ

2250 Benton

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

545 295 484 183

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


282 162


6 - 12" Front and Back

C C C			
	С	С	C
PPM PPM PPM	PPM	/ PPM	PPM
No. No. No.	No.	No.	No.

63 130

Depth Excav. (inch)





Action Date: 8/8/97

Loadout: 8/12/97

Restoration Begins: 8/13/97 Restoration Completed: 8/27/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 31.80 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26 *17-KW *TCM

*Kubota

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Sod Farm

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u>, </u>	
41.34		30.01				120		_

0 - 3" Front and Back

	O O I TOTIL A		
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2252 Benton 436 274

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


423 33

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

85 **604** 227 **3496**

Depth Excav. (inch)



-

Action Date: 10/30/97 Loadout: 11/4/97

Restoration Begins: 11/4/97

Restoration Completed: 11/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 68.25 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
88.73	3.5		16.15	12.85		180		

0 - 3"	Front	and	Back
--------	-------	-----	------

	0 - 0	TOTAL GITTE DOOK		
	A	Α	Α	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	


2254 Benton 319 331 **857** 412 3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

188 199 **770** 397 162 314 6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

43 303 176 410 Depth Excav. (inch)



		•

2256 Benton

Action Date: 10/30/97 Loadout: 10/31/97

Restoration Begins: 10/31/97 Restoration Completed: 11/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2256 Benton

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
60.72	2	31.24	14.77	13.8		240		

Sampling Analysis Project #19531

	0 - 3" Front and Back			
	Α	A	Α	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	

2256 Benton	379	339	398
	645	409	

3 -	6"	Front	and	Back

В	В	В
PPM	PPM	PPM
No.	No.	No.
1101	1101	

218	269	340
463	200	


6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

164	152	153	3
210	193		

Depth Excav.

(inch)





2013/15 Bryan

_ Action Date: 4/1/97 Loadout: 4/2/97

> Restoration Begins: 4/3/97 Restoration Completed: 4/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 94.72 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

QUANTITY SUMMARY FOR

2013/15 Bryan

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	_CU.YDS.		:
123.14	3	62	14.65	44.5		180		

,

Sampling Analysis Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2013/15 Bryan **707 1481**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


454 873

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

299 1660637 144

Depth Excav. (inch)



2023 Bryan

Action Date: 4/28/97

Loadout: 4/30/97

Restoration Begins: 4/30/97 Restoration Completed: 5/19/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 107.85 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

2023 Bryan

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
 (TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
140.23	5	27.41	90.05	27.46	<u> </u>	189		

Sampling hallysis Project #19531

0 - 3" Front and Back

	A	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2023 Bryan **600 1270**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


452 **673**

6 - 12" Front and Back

	1 10/10	and Duo
С	С	С
PPM	PPM	PPM
No.	No.	No.

135 **556** 355 **842**

Depth Excav. (inch)



•		
~		
÷ 4-		
\ /		
•		
\sim		

2027 Bryan

Action Date: 3/26/97

Loadout: 3/28/97

Restoration Begins: 3/29/97 Restoration Completed: 4/24/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 145.11 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

2027 Bryan

OTHER		
CONCRETE		
SOD	CU.YDS.	300
SAND	(TONS)	
	(TONS)	55.35
CA-6	(LONS)	
TOPSOIL	(TONS)	163
BACKFILL	(LOADS)	8
SPECIAL WASTE	(LONS)	188.65

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2027 Bryan **1330**

2700

545



2029/31 Bryan

Action Date: 3/26/97
Loadout: 3/28/97

Restoration Begins: 3/29/97 Restoration Completed: 4/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 118.36 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

QUANTITY SUMMARY FOR

2029/31 Bryan

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	·	
153.89	2	71.09	45.33	25.55		240		

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2029/31 Bryan 395 **693**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

361 **677** 270 **625**


6 - 12" Front and Back

С	С	С	
PPM	PPM	PPM	
No.	No.	No.	

348 **531**

6

Depth Excav. (inch)



-			
9			

2037 Bryan

Action Date: 6/19/97 Loadout: 6/21/97

Restoration Begins: 6/21/97 Restoration Completed: 7/18/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 138.03 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

QUANTITY SUMMARY FOR

2037 Bryan

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
179.45	11	107.35	30.55			508		

Sampling analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2037 Bryan

475

559

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


564 589

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

587 318 490 **825**

Depth Excav. (inch)



DRN. BY:

CHKD. BY:

Scale: 1 in = 20ft

Woodward-Clyde Consultants

2037 BRYAN AVE.

Engineering & sciences applied to the earth & its environment

Resident ID No.

BR2Ø37

₩		

2103 Bryan

Action Date: 11/20/97

Loadout: 11/24/97

Restoration Begins: 11/24/97 Restoration Completed: 12/17/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 159.33 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

2103 Bryan

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER	
 (TONS)	_ (LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	<u>.</u>		
207.13	8	32.26	58.9	90.5		420		-	

Sampling Analysis Project #19531

0 - 3" Front and Back

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2103 Bryan 467 **1574**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

175 **875** 339 **1162**


6 - 12" Front and Back

		11 1G 0G0
С	С	С
PPM	PPM	PPM
No.	No.	No.


268 331

6

Depth Excav. (inch)



X = SAMPLE POINT



•

1715 Chestnut

Action Date: 3/22/97

Loadout: 3/26/97

Restoration Begins: 3/27/97 Restoration Completed: 4/2/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 137.65 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Pedigo Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1715 Chestnut

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND SOD	CONCRETE OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS) CU.YDS.	
178.95	5	47.74	73.09	14.7	283.5	

Sampling malysis Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1715 Chestnut **598 644 766 721**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


311 **852 634 612**

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

234 **2920 1720 1390**

Depth Excav. (inch)



~ 			
<u>ب</u>			

1718/20 Chestnut

Action Date: 9/9/97

_Loadout: 9/11/97

Restoration Begins: 9/12/97 Restoration Completed: 10/21/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 161.02 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

1718/20 Chestnut

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
_	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
	209.33	9	70.63	16.98	34.77		120		

(

Sampling hallysis Project #19531

0	- 3"	Front	and	Back
---	------	-------	-----	------

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

	435	943
	16	21
1718/20 Chesntut	13	16

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


13	56
41	21
275	812
124	41

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

74	80
53	114
304	546
105	623

Depth
Excav.
(inch)



✓		
L. A.		
	·	

1723 Chestnut

Action Date: 10/27/97

Loadout: 10/29/97

Restoration Begins: 10/30/97 Restoration Completed: 11/12/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 218.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

QUANTITY SUMMARY FOR

1723 Chestnut

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
283.73	16	97.44	28.15	14.7	_	1200		

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1723 Chestnut 337 311 413 **1518** 365

3 - 6" Front and Back


В	В	В
PPM	PPM	PPM
No.	No.	No.


371 357 392771 162542 152

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

422 341 256 250 296 Depth Excav. (inch)





1753 Chestnut

Action Date: 8/26/97 Loadout: 9/3/97

Restoration Begins: 9/3/97 Restoration Completed: 9/17/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 181.56 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*KABOTA

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

1753 Chestnut

	SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
L	(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
	236.03	9	47.52	149.3	13.95		477		

(

Sampling Analysis
Project #19531

0 - 3" Front and Back

479

	A	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1753 Chestnut **615** 375 **515 515**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


644 318 **538 580 580**

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

898 239 **689 626**

Depth Excav. (inch)





1929 Cleveland

Action Date: 4/14/97

Loadout: 4/16/97

Restoration Begins: 4/16/97 Restoration Completed: 5/9/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 126.25 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

- *WMI-landfill
- *B. Garcia-trucking
- *Granthum-trucking
- *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

1929 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
 (TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
164.13	1	64.82	83.9	29.15		189		

Sampling halalysis Project #19531

0 - 3	3" F	ront	and	Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

1929 Cleveland **594 687 591** 422 487

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

313 318 **668** 364


6 - 12" Front and Back


С	С	С
PPM	PPM	PPM
No.	No.	No.

149

615

146 **561** Depth Excav. (inch)





-			
~			

1935 Cleveland

Action Date: 7/30/97

Loadout: 8/1/97

Restoration Begins: 8/5/97 Restoration Completed: 8/27/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 75.34 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*Kabota

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm


QUANTITY SUMMARY FOR

1935 Cleveland


SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER	
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.			!
97.95	4	53	27.3			240	=	-	

Sampling Analysis Project #19531

-	0 - 3" Front and Back			3-6"	3-6" Front and Back			6-12" Front and Back		
Street/Number Address	A PPM No.	A PPM No.	A PPM No.	B PPM No.	B PPM No.	B PPM No.	C PPM No.	C PPM No.	C PPM No.	Depth Excav. (inch)
1935 Cleveland	348 413	281 109		390 557	360 378		453 144	348 526		12



X = SAMPLE POINT





Drawn By: EDJ Date: 7/29/98	Checked By: Approved By:
Scale: NTS	Drawing No:

~		

Action Date: 8/1/97

Loadout: 8/6/97

Restoration Begins: 8/6/97 Restoration Completed: 8/27/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 122.98 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*BOMAG

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm


QUANTITY SUMMARY FOR

1939 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
159.88	6	42.78				510		

Sampling Analysis
Project #19531

	0 - 3"	Front a	nd Back	3-6"	Front an	d Back	6-12'	' Front a	nd Back	
Street/Number Address	A PPM No.	A PPM No.	A PPM No.	B PPM No.	B PPM No.	B PPM No.	C PPM No.	C PPM No.	C PPM No.	Depth Excav. (inch)
1939 Cleveland	1070 514	1050	552	369 497	940	391	58 1650	646	43	12



Bl - 81 east of sidewalk & 71 South of sidewalk,

Ba- 121 west of fence 8' north of menent platform

To paved thouse

& Appears that front good was tilled.

-		
_		

Action Date: 11/4/97

Loadout: 11/12/97

Restoration Begins: 11/12/97 Restoration Completed: 11/17/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 89.47 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Schneider-turf farm

QUANTITY SUMMARY FOR

2006 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
116.32	7	47.52		12.85		300		

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

		IG DUCK
В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)

2006 Cleveland


685

436


326 398

611

816



X = SAMPLE POINT





Action Date: 10/6/97 Loadout: 10/10/97

> Restoration Begins: 10/10/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 75.70 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm


QUANTITY SUMMARY FOR

2026 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)_	_(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	1	
98.41	5	44.06		15.05		420		

Sampling Analysis
Project #19531

	0 - 3"	Front a	nd Back	3-6"	Front an	d Back	6-12'	' Front a	nd Back	
Otan ad/Normalian	A	A	A	В	B PPM	B PPM	C PPM	C PPM	C PPM	Depth
Street/Number Address	PPM No.	PPM No.	PPM No.	PPM No.	No.	No.	No.	No.	No.	Excav. (inch)
2026 Cleveland	354	1780		536	1610		192	64		6



Bi 5'S of front walk 19' W of house

15' N to extension of among

لمللم

~			
`_			
	•		
\smile			

Action Date: 10/6/97 _Loadout: 10/9/97

Restoration Begins: 10/9/97

Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 111.71 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2028 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS,		
145.31	6	29.99	15.9			420		

(

Sampling Analysis
Project #19531

0 - 3" Front and Back

	0 0	IG DGOIL	
	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

Depth Excav. (inch)


2028 Cleveland

662

1780

644 2340

67 **673** 85 **1241**



\sim		
<u></u>		
<u>~</u> :		
<u>~</u>		
		•
		·
		·
		•

Action Date: 4/28/97

Loadout: 4/29/97

Restoration Begins: 4/30/97 Restoration Completed: 10/22/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 74.27 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

EASEMENT INFORMATION

This easement was completed after the Temporary Restraining Order (TRO) was lifted.

QUANTITY SUMMARY FOR

2029 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)_	CU.YDS.		
125.54	2	108.91	14.75			480		

Sampling mulalysis
Project #19531

0 - 3" Front and Back

	6 - 6 TTOTE AND BACK						
	Α	Α	Α				
Street/Number	PPM	PPM	PPM				
Address	No.	No.	No.				

2029 Cleveland **995** 194 **686** 485

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

535 104447 519


6 - 12" Front and Back


С	С	C
PPM	PPM	PPM
No.	No.	No.

155 32

6

Depth Excav. (inch)





		•
	•	

Action Date: 8/18/97 _Loadout: 8/20/97

> Restoration Begins: 8/22/97 Restoration Completed: 8/28/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 47.63 cubic yards, which was shipped to WMI-Milam for disposal.

*Equipment utilized during excavation:

*TL-26

*TCM

*X331

*KABOTA

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Grantham-trucking

*Emerald-turf farm

QUANTITY SUMMARY FOR

2055 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
61.92		50.79				320		

Sampling Analysis
Project #19531

2055 Cleveland

0 - 3" Front and Back

	A	A	A	
Street/Number	PPM	PPM	PPM	
Address	No.	No.	No.	

340 **715 1671** 212

3 - 6" Front and Back

В	В	В		
PPM	PPM	PPM		
No.	No.	No.		

235 411


6 - 12" Front and Back

	0 12	1 10116	aria badi
ſ	С	С	С
ľ	PPM	PPM	PPM
	No.	No.	No.


289 194

Excav. (inch)

Depth



X = SAMPLE POINT



:

Action Date: 8/20/97 Loadout: 8/20/97

> Restoration Begins: 8/22/97 Restoration Completed: 9/10/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 66.81 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Emerald Turf Farm

QUANTITY SUMMARY FOR

2057 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
86.86		66.95	34.55			420		

Sampling malysis
Project #19531

2057 Cleveland

0 - 3" Front and Back
A A A
Street/Number PPM PPM PPM
Address No. No. No.

677 552

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.


286 420

6 - 12" Front and Back

C	С	С		
PPM	PPM	PPM		
No.	No.	No.		


100 203

Depth Excav. (inch)



B1 6' to walk into hairs 12' to front of porch B2 25' N ci funce 10' to of garage

Horse Fother wrens = 86%



2056/58 Cleveland

Action Date: 9/30/97

Loadout: 10/1/97

Restoration Begins: 10/2/97 Restoration Completed: 10/21/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 6 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 46.36 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*17-KW

*X331

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Emerald Turf Farm

OHM CORPORATION PROJECT 19531 GRANITE CITY, IL

QUANTITY SUMMARY FOR

2056/58 Cleveland

SPECIAL WASTE	BACKFILL TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS) (TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.	!	
60.28	3		12.32		180		

.

Sampling Analysis Project #19531

0 -	. 3"	Front	and	Back

	O O FIOR GRAD BOOK					
	Α	Α	Α			
Street/Number	PPM	PPM	PPM			
Address	No.	No.	No.			

2056 Cleveland 386 **724** 464 **521**

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

309 **571** 174 **559**


6 - 12" Front and Back

С	С	С
PPM	PPM	PPM
No.	No.	No.

59 **964** 77 186 106 78

Depth Excav. (inch)

6





2100 Cleveland

Action Date: 9/17/97
Loadout: 9/18/97

Restoration Begins: 9/19/97 Restoration Completed: 10/13/97

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 12 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 123.04 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17-KW

*Subcontractors:

*WMI-landfill

*B. Garcia-trucking

*Granthum-trucking

*Schneider Turf Farm

OHM CORPORATION PROJECT 19531 GRANITE CITY, IL

QUANTITY SUMMARY FOR

2100 Cleveland

SPECIA	L WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(T	ONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
15	9.96	5	55.38	34.27	19.11		180	.	

Sampling Analysis
Project #19531

0 - 3" Front and Back

	Α	Α	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

3 - 6" Front and Back

В	В	В
PPM	PPM	PPM
No.	No.	No.

6 - 12" Front and Back

	• .		
-	C	С	С
	PPM	PPM	PPM
	No.	No.	No.

Depth Excav. (inch)


2100 Cleveland

1327

333

610

12



X = SAMPLE POINT



*		
•		
•		
,~		
, ~ \		

2110 Cleveland

Action Date: 4/7/98 Loadout: 4/8/98

Restoration Begins: 4/9/98 Restoration Completed: 4/18/98

- *Stack emission sites were not sampled for verification due to the fact that a predetermined depth for excavation was given to OHM by USACE.
- *An excavation depth of 3 inches was established by USACE prior to work commencing.
- *The excavation of special waste yielded a total of 69.46 cubic yards, which was shipped to WMI-Milam for disposal.
- *Equipment utilized during excavation:

*TL-26

*TCM

*X331

*17KW

- *Subcontractors:
 - *WMI-landfill
 - *B. Garcia-trucking
 - *Granthum-trucking
 - *Schneider Turf Farm

OHM CORPORATION PROJECT 19531 GRANITE CITY, IL

QUANTITY SUMMARY FOR

2110 Cleveland

SPECIAL WASTE	BACKFILL	TOPSOIL	CA-6	CA-7	SAND	SOD	CONCRETE	OTHER
(TONS)	(LOADS)	(TONS)	(TONS)	(TONS)	(TONS)	CU.YDS.		
90.3	11			<u></u>		540		

Sampling analysis Project #19531

	0-3	Front ar	id Back
	Α	A	Α
Street/Number	PPM	PPM	PPM
Address	No.	No.	No.

2110 Cleveland	353	515
	403	446


3 - 6"	Front ar	nd Back
В	В	В
PPM	PPM	PPM
No	No	No.

297	437

6 - 12	" Front a	and Bac
С	С	С
PPM	PPM	PPM
No.	No.	No.

C	•		
PPM	PPM	PPM	
No.	No.	No.	

Depth
Excav.
(inch)



B2- 22' sath of horse & 2' west of sidewalk.

<u></u>			
· · · · · · · · · · · · · · · · · · ·			
_			